

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

OFFICE ENGINEER, MS 43

1727 30th STREET

P. O. BOX 168041

SACRAMENTO, CA 95816-8041

PHONE (916) 227-6300

FAX (916) 227-6282

TTY 711

*Flex your power!
Be energy efficient!*

January 26, 2011

Facsimile: (925) 416-7746

Glenn Bugler, President
Bugler Construction
4847 Hopyard Road, Suite 4, #395
Pleasanton, CA 94588

10-0S2404
10-Tuo-108-58.8
B.O. 1/18/12

Dear Mr. Bugler:

Bugler Construction (Bugler) submitted a bid on contract 10-0S2404 on January 18, 2012. By this letter, the Department notifies Bugler that its bid is nonresponsive because it failed to properly submit the Subcontractor List.

The Subcontractor List form states in part,..."Complete columns 1 and 4 and submit with the bid. Complete columns 2 and 3 and submit with the bid or fax to (916) 227-6282 within 24 hours after the bid opening. Failure to provide complete information in columns 1 through 4 within the time specified will result in a non-responsive bid." Bugler failed to submit the percent of bid item subcontracted, as required in column 3 for Sambrano Traffic Control Inc and Hillside Drilling.

Furthermore, the Department notifies Bugler that its bid is nonresponsive because it failed to properly submit their QP certifications. Bugler failed to submit their QP 3 certification. The bid document specifications states in part.

2-1.05 SSPC QP CERTIFICATION PREAWARD QUALIFICATION

Submit the SSPC QP certification required for cleaning and painting in these special provisions.


If you do not submit the certification with your bid, submit it so that it is received by the Office Engineer no later than 4:00 p.m. on the 2nd business day after bid opening.

If you do not submit the certification within the specified time, the Department finds your bid nonresponsive.

Based on the above, the Department finds your bid is nonresponsive. The Department will proceed to award the contract to the lowest responsible bidder provided all requirements are met.

If you have any questions, please contact Tammy Thomas, Contract Awards Branch Chief, at (916) 227-6228.

Sincerely,


JOHN C. McMILLAN
Deputy Division Chief
Office Engineer
Division of Engineering Services

Attachment

STATE OF CALIFORNIA • DEPARTMENT OF TRANSPORTATION
SUBCONTRACTOR LIST
 DES-OE-0102.2 (REV 3/2011)

Bidder Name: Bullock Construction

The bidder must identify each subcontractor performing work in an amount in excess of 1/2 of 1 percent of the total bid or \$10,000, whichever is greater (Pub Cont Code § 4100 et seq.). Complete columns 1 and 4 and submit with the bid. Complete columns 2 and 3 and submit with the bid or fax to (916) 227-6282 within 24 hours after the bid opening. Failure to provide complete information in columns 1 through 4 within the time specified will result in a nonresponsive bid.

Column 1: Business Name and Location	Column 2: Bid Item Nos.	Column 3: Percentage of Bid Item Subcontracted	Column 4: Description of Subcontracted Work
RFB PROTECTIVE COATINGS LANSING, A JEFFCOY VALLE 30, CA CONTRACT CONTROL, FAY	28	100%	COAT STEEL BEAMS
GENI SANTA ANA, CA FARMAN VALLEY	2	100%	PREPARE WALP
SAMBRANO TRAFFIC CONSTRUCTION, INC WILTON CA	9	100%	TRAFFIC CONTROL (FLAGGING)
HILLSIDE DRILLING RICHMOND	23		DRILL CION
HILLSIDE DRILLING RICHMOND	24		TIEBACK ANCHORS
LENTILLINE STRIPING ELIAGROVE, CA	39	100%	INTERMEDIATE TRAFFIC STRIPE

ADA Notice For individuals with sensory disabilities, this document is available in alternate formats. For information call (916) 654-8410 or TDD (916) 654-3880 or write Records and Forms Management, 1120 N Street, MS-89, Sacramento, CA 95814.

**** Transmit Conf. Report ****

P. 1
CAL/TRANS CONTR AWARDS Fax 916-227-6282

Jan 26 2012 02:47pm

Fax/Phone Number	Mode	Start	Time	Page	Result	Note
919254167746	Normal	26:02:47pm	0' 26"	2	# 0 K	

STATE OF CALIFORNIA—BUSINESS, TRANSPORTATION AND HOUSING AGENCY

EDMUND G. BROWN Jr., Governor

DEPARTMENT OF TRANSPORTATION
DIVISION OF ENGINEERING SERVICES
OFFICE ENGINEER, MS 43
1727 30th STREET
P. O. BOX 168041
SACRAMENTO, CA 95816-8041
PHONE (916) 227-6300
FAX (916) 227-6282
TTY 711



*Flex your power!
Be energy efficient!*

January 26, 2011

Facsimile: (925) 416-7746

Glenn Bugler, President
Bugler Construction
4847 Hopyard Road, Suite 4, #395
Pleasanton, CA 94588

10-0S2404
10-Tuo-108-58.8
B.O. 1/18/12

Dear Mr. Bugler:

Bugler Construction (Bugler) submitted a bid on contract 10-0S2404 on January 18, 2012. By this letter, the Department notifies Bugler that its bid is nonresponsive because it failed to properly submit the Subcontractor List.

The Subcontractor List form states in part, "...Complete columns 1 and 4 and submit with the bid. Complete columns 2 and 3 and submit with the bid or fax to (916) 227-6282 within 24 hours after the bid opening. Failure to provide complete information in columns 1 through 4 within the time specified will result in a non-responsive bid." Bugler failed to submit the percent of bid item subcontracted, as required in column 3 for Sambrano Traffic Control Inc and Hillside Drilling.

Furthermore, the Department notifies Bugler that its bid is nonresponsive because it failed to properly submit their QP certifications. Bugler failed to submit their QP 3 certification. The bid document specifications states in part.


2-1.05 SSPC QP CERTIFICATION PREAWARD QUALIFICATION

Submit the SSPC QP certification required for cleaning and painting in these special provisions. If you do not submit the certification with your bid, submit it so that it is received by the Office Engineer no later than 4:00 p.m. on the 2nd business day after bid opening. If you do not submit the certification within the specified time, the Department finds your bid nonresponsive.

Based on the above, the Department finds your bid is nonresponsive. The Department will proceed to award the contract to the lowest responsible bidder provided all requirements are met.

If you have any questions, please contact Tammy Thomas, Contract Awards Branch Chief, at (916) 227-6228.

Sincerely,


JOHN C. McMILLAN
Deputy Division Chief
Office Engineer
Division of Engineering Services

Attachment