

California State Department of Transportation
Division of Toll Bridge Program



San Francisco-Oakland Bay Bridge
East Span Seismic Safety Project

**SKYWAY
INFORMATION HANDOUT**

CD1

Skyway Contract No.04-012024
04-SF-80-13.9-14.3
ALA-80-0.0-1.6

CD1 CONTENT (1 of 3)

- **San Francisco-Oakland Bay Bridge East Span As-Built Drawings**, prepared for T.Y. Lin International/Moffatt & Nichol Engineers A Joint Venture by Dokken Engineering (see CONTENT OF AS-BUILT FOLDER- 4 pages),
Foldername:asbuilt Filesize:255MB(61 files)
- **(CSWPPP) Conceptual Storm Water Pollution Prevention Plan**, dated August 2000 by Caltrans Environmental Engineering Branch,
Filename:cswppp.pdf Filesize:1.69MB
- **Phase I Archeological Survey Report - Maritime Archaeology (SFOBB) San Francisco-Oakland Bay Bridge East Span Pile Installation Demonstration Project**, dated September 1999 prepared by James M. Allan of William Self Associates, Reviewed by Michael W. Davis of Parsons Brinckerhoff, Inc. & Approved by Mara Melandry for Steven Hulsebus of Caltrans District 4,
Filename:archaeo1.pdf Filesize:9.61MB

CD1 CONTENT (2 of 3)

- **Addendum Archeological Survey Report- Maritime Archaeology, San Francisco-Oakland Bay Bridge East Span**

dated December 6, 1999 Memorandum Report prepared by Jim Allan of William Self Associates prepared for Mara Melandry, & Janet Pape of Caltrans

Filename:archaeo2.pdf **Filesize:**877KB

dated March 2000, prepared by James M. Allan of William Self Associates, Reviewed by Michael W. Davis of Parsons Brinckerhoff & Approved by Mara Melandry for Steven Hulsebus of Caltrans District 4,

Filename:archaeo3.pdf **Filesize:**12.6MB

dated August 17, 2000 Memorandum Report prepared by Jim Allan of William Self Associates prepared for Janet Pape of Caltrans

Filename:archaeo4.pdf **Filesize:**1.04MB

- **(SFOBB) San Francisco-Oakland Bay Bridge East Span Underwater Debris Diagram,**

dated May, 2001(Note: Debris Location is based on "Phase I Archeological Survey Reports-Maritime Archeology " and "Addendums Archeological Survey Report-Maritime Archeology" on CD2)

Filename:debris.pdf **Filesize:**458KB

CD1 CONTENT (3 of 3)

- **(SFOBB) San Francisco-Oakland Bay Bridge East Span Survey Information:**
Control Diagram, dated April 25, 2001, provided by Caltrans Survey Branch,
Filename:survey1.pdf **Filesize:**3.29MB
- **Oakland Mole Survey Information Volume 1 of 2:**
Summary of Photo Control Points and Survey Notes, date of Survey January 15, 1997 & April 1997, provided by Caltrans Survey Branch,
Filename:survey2.pdf **Filesize:**7.25MB
- **Oakland Mole Survey Information Volume 2 of 2:**
Control points on Aerial Photos, date of Survey January 15, 1997 & April 1997, provided by Caltrans Survey Branch,
Filename:survey3.pdf **Filesize:**3.03MB
- **US Coast Guard Private Aids to Navigation Sample Application Form,**
Filename:uscgform.pdf **Filesize:**192KB

Content of As-Built Folder (1 of 4)

Readme

- Bent E23 to E39 Retrofit (Contract No. 04-043431)
- Bent E4-Reconstruction of Top Struts (Contract No. 04-37)
- Cable Realign Sta. 301+86 to Toll Plaza (Cont. 52-15TC1)
- Camera Installation (Contract No. 04-030844)
- Cant. Struct. L. Chord Damage Repair (Cont. 04-035104)
- Deck Drainage Improvements-YBI (Cont.04-0426404)
- E. Bay L. Deck Truss Scaffold for 288' Span (Cont. 60-15BBC1)
- E. Bay Travel Scaffold Rail Improvements (Cont.04-029404)
- E. Bay U. Deck Trav. Track Spans YBI-E1 (Cont.51-15TC2)
- Earthquake Repairs-Pier E18-E22 (Contract No. 04-190054)
- Earthquake Repairs - Pier E9 (contract No. 04-190014)
- Earthquake Restrainers (Contract No. C-64158)
- East Bay 288' Span Truss Web Scaffold (Cont. 04-026704)
- East Bay Fenders (Contract No. 04-0474)
- East Bay Ladders and Walkways (Contract No. 04-025504)
- East Bay Lower Deck Travelers (Contact No.62-15BBC2)
- Electrical Alterations (Contract No. 04-44122)

Content of As-Built Folder (2 of 4)

- Expansion Grating Shields (Contract No. C-54066)
- Fender Repairs W5,E4 and E5 (Contract No. 65-15U38C2)
- Glare Screen (Contract No. 04-64128)
- Int. Seis. Retr. E. Bay Truss Spans E17-E22 (Cont.04-3004)
- Int. Seis. Retr. E. Bay Truss Spans E9-E16 (Cont. 04-3004)
- Int. Seis. Retr. East Bay 288' Truss YBI (Cont. 04-043004)
- Int. Seis. Retr. East Bay Cant. Truss (Cont. 04-043004)
- Interim Seis. Retr. East Bay 504 Trusses (Cont. 04-043004)
- Interim Seis. Retr. East Bay YBI Viaduct (Cont. 04-043004)
- Interim Seismic Retrofit Roadway Plans (Cont. 04-043004)
- Lower Deck Relamping (Contract No. 04-122054)
- Maintenance Roads (Contract No. 004338)
- Maintenance Safety Improvements (Contact No.04-001644)
- Marine Radar Beacon (Contract No. 004384)
- Mole Air and Water Lines (Contact No.04-4065)
- Mole Shoreline Restoration & Improvements (Cont. 040056)

Content of As-Built Folder (3 of 4)

- Pier E9 Seismic Retrofit (Contract No. 190024)
- Proposed Fender Repairs (Contract No. 61-14BBC2)
- Reconstr. Exp. Gratings Upper Deck (Contract No. 04-4093)
- Reconstruct Expansion Joints (Contract No. C-64123)
- Reconstruction-Track Removal (Contract No. C-4003)
- Reconstruction Deck Paving-East Bay (Contract No. 04-4011)
- Reconstruction Deck Surfacing (Contract No. 04-4033)
- Reconstruction Lower Deck Lighting (Contract No. 04-4027)
- Reconstruction Lower Deck Surfacing (Contract No. 04-4024)
- Reconstruction Sealing Upper Deck Joints (Cont. 04-4036)
- Reconstruction Steel Work-East Bay (Contract No. 04-4030)
- Reconstruction Structure-YBI (Contract No. 04-4029)
- Reconstruction Upper Deck Lighting (Contract No. C4070)
- Repair of Damaged Member U10-L10 (Contract No. 04-20777)
- Resurface Lower Deck Paving & Striping (Cont. 04-025204)
- Resurfacing Upper Deck (Contract No. 04-014504)

Content of As-Built Folder (4 of 4)

- SFOBB Seismic Retrofit (Contract No. 04-01731)
- South Railing Repair - Span E10 (Contract No. 04-04154)
- Substructure - Girder Span on Mole (Contract No. 8)
- Substructure East Bay Crossing (Contract Nos. 04-4, 04-4A)
- Superstructure East Bay Crossing (Contract No. 04-7)
- Traveler Rail Support Revisions-East Bay (Cont. 04-030304)
- Truss & Railing repair Spans W1,E10,E18 (Cont. 04-04139)
- Truss and Railing Repair, Span E11 (Contract No. 04-4168)
- Upper Deck Lighting Stage 1 (Contract No. 04-004053)
- YB1 Slide Repair - Bent 50 (Contract No. C-64152)
- Yerba Buena Crossing (Contract No. 04-5)

Contact us

If you have any questions please contact:

The Toll Bridge Program Duty Senior

District 04 Office

111 Grand Avenue

Oakland CA 94612

Telephone Number: (510) 286-5549

e-mail address

duty_senior_tollbridge_district04@dot.ca.gov