

**Week Ending Dec. 12/08**

**Problems encountered this week:**

1. Finalization of grillage plate type "B" profile.
2. Architectural housing bolted splice across OBG skin plate profile transition (girder faces "C", "H", "I", and "G")
3. Stiffener plate transition on girder faces "C" and "H" in relation to weld access.
4. Finalizing access openings in bolted arch. housing at PP120, PP121, PP122 and PP123.
5. Trying to rationalize the function and purpose of latest T.Y. Lin/Caltrans 3D model (NAVISWORKS).