

Week Ending Jan. 2/09

Problems encountered this week:

Combination of in and out of plane kinks in WT at bolted architectural housing splice.