



SSE 45 AND 46

12" X 14" X 6" SSE


14" X 18" X 1/2" METAL PLATE



- ① DRILL AND TAP STEEL PLATE 1/4" 20. BOLT SSE TO PLATE USING STAINLESS STEEL 1/4" 20 X 1" BOLTS
- ② DRILL 7/16" HOLE IN STEEL PLATE, BOLT THRU STEEL PLATE TO STRUT USING 3/8" X 1/2" BOLTS.
- ③ DRILL AND TAP STEEL PLATE 1/4" 20. BOLT SENSOR MOUNTING PLATE THRU SSE TO STEEL PLATE USING STAINLESS STEEL 1/4" 20 X 1" BOLTS
- ④ SECURELY FASTEN STRUT TO BEAM FLANGE BY EITHER WELDING OR BOLTING.



SSE 44 AND 47



SEE NOTES Δ AND DETAILS ON SHEET 1
FOR SSE'S 45 AND 46