

Job Stamp 04-0120F4 SFOBB SAS

Report No.	Should be typed			
Date	12/13/2007			
Inspectors	Start	0700	Stop	1500
Hours				
Shift Hours	Start	0630	Stop	1500

Description of Operation:

- Tim and Jorge started the coupling with their own risk, because they are waiting approval from Caltrans on certifications (see Figure 1). Make sure that they apply 400 lb torque for the coupling (see Figure 2). Marked with orange painter (see Figure 3)

Figure 1



Figure 2





Figure 3



Inspector:

SeongHyeok Song

Trans Engineer (C)/Asst. Struct. Rep