

STATE OF CALIFORNIA – DEPARTMENT OF TRANSPORTATION
RESIDENT ENGINEER'S DAILY REPORT
ASST. RESIDENT ENGINEER'S DAILY REPORT
 DC-CEM-4501-CUSTOM



04-0120F4
04-SF-80-13.2/13.9
SAS

RESIDENT ENGINEER'S DAILY REPORT – FILE CAT. 45
 ASST. RESIDENT ENGINEER'S DAILY REPORT – FILE CAT. 46

REPORT NO.: 418 to 422	DATE: 2/4 to 2/8/08	S <input type="checkbox"/> M <input type="checkbox"/> T <input type="checkbox"/> W <input type="checkbox"/> T <input type="checkbox"/> F <input type="checkbox"/> S <input type="checkbox"/> (Circle Day)
SHIFT HOUR: START; 07:00 STOP; 15:30	TEMPERATURE: MIN; NA MAX; NA	
WEATHER: (NA – See Weekly Statement of Working Days)		

Monday: 2/4/08 0700 - 1530 = 8 hrs

- Worked on the cost estimate and cost estimate summaries for CCO 35 and 36S0
- Alex Schmitt asked about CCO 24S0 plan sheets that were sent to ABF. I told Alex that Skyway's CCO 22 plan sheets were incorporated into the plan sheets that were sent to ABF except that the as-built conditions are not shown and the additional work of removing and replacing the existing traveler rail, and installing the mounting plate in concrete at the Skyway are also not addressed.

Tuesday: 2/5/08 0700 - 1530 = 8 hrs

- Worked on the cost estimate for CCO 36S0 and cost estimate summaries for CCO 37, 38S0, and 39
- Attended CCO meeting with ABF

Wednesday: 2/6/08 0700 - 1530 = 8 hrs



- Evaluated CCO 24 S0 documents missing from the CCO package to include the removal and replacement of the existing traveler rail, furnishing and installing mounting plate in concrete section of the Skyway, replacing fasteners, furnishing and installing additional hardware for the rail that was left out in the Skyway project. Two additional plan sheets that show the length of rail at both directions need to be furnished to ABF so they can quantify the amount of rail in the Skyway transition.
- Attended China debrief meeting and internal CCO meeting

Thursday: 2/7/08 0700 - 1530 = 8 hrs

- No access to PMIV and network drives that were down in the morning
- Attended SAS safety and staff meeting
- Spoke with Sam Choy to request price quote for the lump sum portion of CCO 60 (Cable Band Display). Sam will prepare it and forward to Caltrans for review and approval.
- Worked on the cost estimate summary for CCO 40

Friday: 2/8/08 0700 - 1530 = 8 hrs

- Worked on the cost estimate summaries for CCO 40, 45, 46, 47 and 49

SIGNATURE 	TITLE Consultant Engineer, SAS 
--	--

REC-08 FEB-23 #003575