

STATE OF CALIFORNIA	Job Stamp	7-day Const. Calendar	Day No. 464
DEPARTMENT OF TRANSPORTATION	SFOBB SAS	Project Work Day No.	Day No. 674
Form HC-10A (Rev. 6/80)	04-0120F4	Date	03/21/2008

Inspectors Hours	Start	0700	Stop	1530
Shift Hours	Start	0630	Stop	1500

ASSISTANT RESIDENT ENGINEER'S

CONTRACTOR – ABFJV

HOURS - ITEM NO.													
EQUIPMENT AND/OR LABOR:			48 – Bar Reinforcing Steel (Bridge)								IDLE OR DOWN	REMARKS	
Equip. #	NO. MEAN	DESCRIPTION (Of Equipment or Labor)										Name	Contractor
		Regional Steel											
1	1	Superintendent	0									Gaige, Lance	RSC
2	1	Foreman	0									Van Brusselen, Jon	RSC
3	1	Ironworker	0									Jobe, Jason	RSC
4	1	Ironworker	0									Manzano, Jose	RSC
5	1	Ironworker	0									Lopez, Jorge	RSC
6	1	Ironworker	0									Greenlee, Tim	RSC
7	1	Ironworker	0									Rodriguez, Ernesto	RSC
8	1	Ironworker	0									Gomez, Daniel	RSC
9	1	Ironworker	0									Balderrama, Julio	RSC
10	1	Ironworker	0									Ortiz, Roberto	RSC
11	1	Ironworker	0									Mortenson, Kurt	RSC
12	1	Ironworker	0									Bell, Joe	RSC
13	1	Ironworker	0									Vasquez, Reynaldo	RSC
14	1	Ironworker	0									Stockton, Luke	RSC
15	1	Ironworker	0									Quiroz, Victor	RSC
16	1	Ironworker	0									Raprasnussen, John	RSC
17	1	Ironworker	0									Leon, Moises	RSC

Weather: Sunny, mild, wet ground, Hi 60 F Lo 46 F.

Description of Operation:

ABF

See L. Mathur's diary for labor, equipment and daily activities. Also see M. Bruce's diary for additional comments.

- Inspected L & T bars for concrete remaining on rebar after ABF has attempted to clean using a impact tool. Additional cleaning is required. See photos below.

Daily for Regional Steel

RSC is not on site today.


Office Work

- Checked and responded to email.
- Continued to work on rebar/COC spreadsheet to compare COC vs. delivered rebar.

NOTES:

Inspector:


Pamela Gagnier

A handwritten signature in blue ink, appearing to be 'P. Gagnier', written over a horizontal line.

Trans Engineer (C)/Asst. Struct. Rep



L & T rebar in south column region. Requires additional concrete removal.



L & T rebar in south column region. Requires additional concrete removal.