



STATE OF CALIFORNIA - DEPARTMENT OF TRANSPORTATION

ENGINEER'S DAILY REPORT

LAN Engineering Consultant

at 4-10-08

REPORT NO.	453 (7-day)	DATE	March 10, 2008	<i>at</i> T W T F S S (DAY)
NORMAL WORK HOUR:	START: 7:00AM	STOP: 3:30PM	WEATHER:	OVERCAST/SUNNY
LOCATION :	Construction Field Office :	333 Burma Road, Oakland 94607		
	Working Drawing Campus Office :	375 Burma Road, Oakland 94607		

04-SF-80-13.2/13.9
 Contract No. 04-0120F4
 {SAS Superstructure}

Caltrans Supervisor:
 Gary Lai
 Senior Bridge Engineer

Office Work:

- ❖ China Connection (Scott Kennedy)
 - Sent Tracking Chart Attachments to Scott three at a time to make sure he received them.
 - See Attachments.
- ❖ Called Maxwell Takaki (PB).
 - Checked with Max to make sure he got my comments on the shop drawing list for Monday's meeting.
 - Talked to Max about the Tracking chart and some of the conflicts I found and the need to review my comments on the Chart sent to China.
 - I informed Max that I would cover some of the items on Tuesday with Abdi.

Any questions or comments you can reach me at (916) 919-7158. My E-Mail address is Mike.Travis@LANEngineering.com or Michael.Travis@dot.ca.gov

END OF REPORT

SIGNATURE

Work hours- None Declared * See March 08, 2008 Diary

Name	Michael F. Travis	TITLE	Electrical Engineer – LAN Engineering
------	-------------------	-------	---------------------------------------

 Attachments can contain viruses that may harm your computer. Attachments may not display correctly.

Mike Travis

From: Mike Travis **Sent:** Mon 3/10/2008 7:30 AM
To: skennedy@sasoverseasteam.com
Cc: Gary J Lai; Bill Shedd
Subject: MEP Attachments #7
Attachments:  SP_300_REF.pdf(932KB)  SP_571_REF.pdf(1MB)  X107_REF.pdf(947KB)  X112_REF.pdf(798KB)

Scott,

Attached are the MEP attachments in multiple email packages.(1-7)

I am out of the office until Tuesday Morning so if there are any questions let me know tomorrow.

Any questions or comments let me know.

Michael Travis

Supervising Electrical/Structural Construction Engineer

Lim And Nascimento Eng. Corp.

11344 Coloma Road, Suite 590

Gold River, CA 95670

916.919.7158 cell

 Attachments can contain viruses that may harm your computer. Attachments may not display correctly.

Mike Travis

From: Mike Travis **Sent:** Mon 3/10/2008 7:18 AM
To: skennedy@sasoverseasteam.com
Cc: Gary J Lai; Bill Shedd
Subject: MEP Attachments #6
Attachments:  PL_1452_REF.pdf(956KB)  PL_1453_REF_R1.pdf(889KB)  SP574_REF.pdf(1MB)

Scott,

Attached are some additional attachments for your reference.

Michael Travis

Supervising Electrical/Structural Construction Engineer

Lim And Nascimento Eng. Corp.

11344 Coloma Road, Suite 590

Gold River, CA 95670

916.919.7158 cell

 Attachments can contain viruses that may harm your computer. Attachments may not display correctly.

Mike Travis

From: Mike Travis **Sent:** Mon 3/10/2008 7:15 AM
To: skennedy@sasoverseasteam.com
Cc: Gary J Lai; Bill Shedd
Subject: MEP Attachments #6
Attachments:  PL_1303_REF.pdf(166KB)  PL_1370_REF.pdf(132KB)  PL_1374_REF.pdf(154KB)

Scott,
Ataached are some additional attachments for your reference.

Michael Travis
Supervising Electrical/Structural Construction Engineer

Lim And Nascimento Eng. Corp.
11344 Coloma Road, Suite 590
Gold River, CA 95670
916.919.7158 cell

 Attachments can contain viruses that may harm your computer. Attachments may not display correctly.

Mike Travis

From: Mike Travis

Sent: Mon 3/10/2008 7:11 AM

To: skennedy@sasoverseasteam.com

Cc: Gary J Lai; Bill Shedd

Subject: MEP Attachments references #5

Attachments:  PL1126_REF.pdf(1MB)  PL1302A_REF.pdf(196KB)  PL_1029_REF.pdf(817KB)

Scott,

Attached are additional reference attachments.

Michael Travis

Supervising Electrical/Structural Construction Engineer

Lim And Nascimento Eng. Corp.

11344 Coloma Road, Suite 590

Gold River, CA 95670

916.919.7158 cell

 Attachments can contain viruses that may harm your computer. Attachments may not display correctly.

Mike Travis

From: Mike Travis **Sent:** Mon 3/10/2008 7:06 AM
To: skennedy@sasoverseasteam.com
Cc: Bill Shedd; Gary J Lai
Subject: MEP Attachments #4
Attachments:  LD_29_REF.pdf(1MB)  LD_33_REF.pdf(1MB)  PL24_REF.pdf(668KB)

Scott,

Attached are some of the MEP reference Attachments for the chart.

Michael Travis

Supervising Electrical/Structural Construction Engineer

Lim And Nascimento Eng. Corp.

11344 Coloma Road, Suite 590

Gold River, CA 95670

916.919.7158 cell

 Attachments can contain viruses that may harm your computer. Attachments may not display correctly.

Mike Travis

From: Mike Travis **Sent:** Mon 3/10/2008 6:58 AM
To: skennedy@sasoverseasteam.com
Cc: Bill Shedd; Gary J Lai
Subject: MEP Attachments #3
Attachments:  DP_656A_REF.pdf(813KB)  DP_664_REF.pdf(924KB)  EP35_REF.pdf(999KB)

Scott,

Attached are some additional attachments for you reference.

Michael Travis

Supervising Electrical/Structural Construction Engineer

Lim And Nascimento Eng. Corp.

11344 Coloma Road, Suite 590

Gold River, CA 95670

916.919.7158 cell

 Attachments can contain viruses that may harm your computer. Attachments may not display correctly.

Mike Travis

From: Mike Travis **Sent:** Mon 3/10/2008 6:53 AM
To: skennedy@sasoverseasteam.com
Cc: Gary J Lai; Bill Shedd
Subject: MEP Attachments #2
Attachments:  DP36_REF.pdf(651KB)  DP655A_REF.pdf(1MB)  DP662_REF.pdf(902KB)

Scott,

Attached are some of the attachments.
I could not send all at one time.

Michael Travis
Supervising Electrical/Structural Construction Engineer

Lim And Nascimento Eng. Corp.
11344 Coloma Road, Suite 590
Gold River, CA 95670
916.919.7158 cell

 Attachments can contain viruses that may harm your computer. Attachments may not display correctly.

Mike Travis

From: Mike Travis **Sent:** Mon 3/10/2008 6:53 AM
To: skennedy@sasoverseasteam.com
Cc: Gary J Lai; Bill Shedd
Subject: MEP Attachments #1
Attachments:  140R03BL_DP46.PL30_REF.pdf(1MB)  BP_312_REF.pdf(1MB)  BP_314_REF.pdf(1MB)

Scott,

The lump sum attachments did not make it so will send a few at a time.

Michael Travis
Supervising Electrical/Structural Construction Engineer

Lim And Nascimento Eng. Corp.
11344 Coloma Road, Suite 590
Gold River, CA 95670
916.919.7158 cell