

|                              |           |                       |             |
|------------------------------|-----------|-----------------------|-------------|
| STATE OF CALIFORNIA          | Job Stamp | 7-day Const. Calendar | Day No. 504 |
| DEPARTMENT OF TRANSPORTATION | SFOBB SAS | Project Work Day No.  | Day No. 704 |
| Form HC-10A (Rev. 6/80)      | 04-0120F4 | Date                  | 04/30/2008  |

|                  |       |      |      |      |
|------------------|-------|------|------|------|
| Inspectors Hours | Start | 0700 | Stop | 1530 |
| Shift Hours      | Start | 0630 | Stop | 1500 |

ASSISTANT RESIDENT ENGINEER'S

CONTRACTOR - ABFJV

HOURS - ITEM NO.

| EQUIPMENT AND/OR LABOR: |          |                                     | 48 - Bar Reinforcing Steel (Bridge) | IDLE OR DOWN | REMARKS                |
|-------------------------|----------|-------------------------------------|-------------------------------------|--------------|------------------------|
| Equ. #                  | NO. MEAN | DESCRIPTION (Of Equipment or Labor) |                                     |              |                        |
|                         |          | Regional Steel                      |                                     |              | Name Contractor        |
| 1                       | 1        | Superintendent                      | 0                                   |              | Gaige, Lance RSC       |
| 2                       | 1        | Foreman                             | 0                                   |              | Van Brusselen, Jon RSC |
| 3                       | 1        | Ironworker                          | 0                                   |              | Vallarreal, Jose RSC   |
| 4                       | 1        | Ironworker                          | 0                                   |              | Manzano, Jose RSC      |
| 5                       | 1        | Ironworker                          | 0                                   |              | Lopez, Jorge RSC       |
| 6                       | 1        | Ironworker                          | 0                                   |              | Greenlee, Tim RSC      |
| 7                       | 1        | Ironworker                          | 0                                   |              | Rapasmussen, John RSC  |
| 8                       | 1        | Ironworker                          | 0                                   |              | Gomez, Daniel RSC      |
| 9                       | 1        | Ironworker                          | 0                                   |              | Balderrama, Julio RSC  |
| 10                      | 1        | Ironworker                          | 0                                   |              | Espinoza, Sal RSC      |
| 11                      | 1        | Ironworker                          | 0                                   |              | Mortenson, Kurt RSC    |
| 12                      | 1        | Ironworker                          | 0                                   |              | Bell, Joe RSC          |
| 14                      | 1        | Ironworker                          | 0                                   |              | Stockton, Luke RSC     |
| 15                      | 1        | Ironworker                          | 0                                   |              | Quiroz, Victor RSC     |

Weather: P. Cloudy, mild, dry ground, Hi 75 F Lo 49 F.

Description of Operation:

ABF

- See L. Mathur's diary for labor, equipment and daily activities.

Daily for Regional Steel

RSC was not on the job site today working on Temporary Towers.

NOTES:

Discussed with TYLin if it is acceptable to add small matt in jacking saddle southeast quad there is ~ 9" space between form and rebar due to 1.05 degree shift in forms. TYLin finds this acceptable. See photo below.

P.Gagnier

RECT 08 MAY 31 #004984


Arrived on site (6:30am) to meet with Tim Greenlee (RSC) to discuss small matt for jacking block and punch list items. Tim unable to meet rescheduled for tomorrow.

Office


Attended weekly concrete meeting.  
Check email.

**Inspector:**

Pamela Gagnier



Trans Engineer (C)/Asst. Struct. Rep



~ 9" space between rebars and form at southeast jacking block.