

Punch List RSC:


- Cut bars west wall
- Provide east/west support – prevent movement in #29 vertical transverse bars w/i jacking saddle intersection.
- Tie #29, #25 vertical bars in longitudinal wall west side.
- Cut bury bar against forms southwest jacking saddle block vertical face.
- Add dobies southwest wall.

Office

Attend bi-weekly safety meeting.
Check email.

Inspector:

Pamela Gagnier



Trans Engineer (C)/Asst. Struct. Rep