





EA	04-0120F4
Co-Rte-KP (PM)	SF-080-13.2/13.9 (8.2/8.7)
Structure Rep.	Rick Morrow




File Name:	Sept-29-2008 W2 Cap 004
Date:	09-29-08
By Int:	M Bruce

Description: Piledrivers cut 4"x6" support beams to facilitate the short vertical PT bar template installation. A 2"x6" ledger beam was used to try and maintain the alignment of the bars at the top. The batter of the long vertical bars should be checked prior to concrete placement.

File Name:	Sept-29-2008 W2 Cap 008
Date:	09-29-08
By Int:	M Bruce

Description: Potential conflict with CBT-2/6 and E-40/41B at W2E looking south.



File Name:	Sept-29-2008 W2 Cap 009
Date:	09-29-08
By Int:	M Bruce

Description: Potential conflict with CBT-2/6 and E-40/41B at W2E looking west.

File Name:	Sept-29-2008 W2 Cap 011
Date:	09-29-08
By Int:	M Bruce

Description: Drainage pipes seen connected to the W2E cable tie-down pipes.