

State of California
Department of Transportation
Assistant Resident Engineer's Daily Diary
For: Stanley Ku
Week of 12/24/12-12/28/12
04-0120F4

12/24/2012 Monday Fine

Bill Casey asked me to proceed with thumb turn lock and start punch list on tower. I e-mailed Darryl on reasoning and specifications for CCO 286. I asked Mohammad to start working on the punch list.

12/25/2012 Tuesday

Christmas Day

12/26/2012 Wednesday

Personal Day

12/27/2012 Thursday Fine

I attended safety meeting. Mohammad and I installed 8mm and 10mm thick door seals at elevation 89m. With an effort, the door with 8mm thick door seal could be sealed properly. However, the strike plate could not be rest on the "built-up" with 10mm door seal. The strike plate rested on the back of door frame.

12/28/2012 Friday Fine

I studied details for tower access doors to find out why support plates for door hinges show signs of corrosion although they were painted. It is possible that the friction between washers and support plates damages paints and base metal was exposed for corrosion.



1/11/2013