

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493


Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.15**SOURCE INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** SIR-000016**Date Inspected:** 19-Jan-2007**Project Name:** SAS Superstructure**OSM Arrival Time:** 800**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

Quality Control Contact: Lu Jian Hua
Material transfer: Yes No N/A
Stock Transfer: Yes No N/A
Rebar Test Witness: Yes No N/A

Quality Control Present: Yes No
Sampled Items: Yes No N/A
OK to Cut: Yes No N/A
Delayed/Cancelled: Yes No N/A

Other: Mechanical Testing Observation**Bridge No:** 34-0006**Component:** N/A**Bid Item:****Lot No:****Summary of Items Observed:**

Caltrans Quality Assurance (QA) Inspector participated with Mr. Mark Wright in witnessing the mechanical testing for HP-2006129 and HP-2006131. Caltrans QA Inspector, Mr. Mark Wright Welding Witness Report (TL6032) for additional information, dated 01-19-2007. The following digital pictures illustrate machined test specimens.

**Summary of Conversations:**

ZPMC Quality Control Inspector, Mr. Lu Jian Hua informed Caltrans Quality Assurance (QA) that they would be performing mechanical test identified as HP-2006129 and HP-2006131.

SOURCE INSPECTION REPORT

(Continued Page 2 of 2)

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659,, who represents the Office of Structural Materials for your project.

Inspected By:	Hasler, Mike	Quality Assurance Inspector
----------------------	--------------	-----------------------------

Reviewed By:	Wright, Mark	QA Reviewer
---------------------	--------------	-------------