

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.15**SOURCE INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** SIR-002366**Date Inspected:** 15-Dec-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island**Location:** Changxing Dao, Shanghai**Quality Control Contact:** William (Bill) Oak**Quality Control Present:** Yes No**Material transfer:** Yes No N/A**Sampled Items:** Yes No N/A**Stock Transfer:** Yes No N/A**OK to Cut:** Yes No N/A**Rebar Test Witness:** Yes No N/A**Delayed/Cancelled:** Yes No N/A**Other:** Coating Inspection**Bridge No:** 34-0006**Component:** Office, OBG 8AE, Sub-Assemblies**Bid Item:** 77, 78, 79**Lot No:** B265**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials (OSM) Quality Assurance (QA) NACE III coating inspector, Mr. James Lumley arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island in Shanghai, China. The purpose of the coating inspections are to monitor the surface preparation and coating applications for the SAS Bay Bridge project. This QA NACE III coating inspector observed the following:

Office,

Review and sign project documentation in ABF Satellite off near Blast Shop #1.

OBG 8AE

Base Metal surfaces were pre-blasted for a VT inspection of welds and base metal defects. Caltrans QA Larry Viars, Tim McClendon and Mike Hassler performed VT inspection and mapped accordingly.

Sub-Assemblies

Repairs were performed to Suspender Brackets SB16W AND SB26W after removal from the corresponding lifts for installation of Sea Fasteners. Surfaces were completely re-abrasive blasted to Base Metal and an SSPC SP-10 condition and Interzinc 22 re-applied. Undercoat was inspected for runs and sags and mud crack and found to be in general compliance minor touch up of undercoat currently being performed.

Note: All inspections were performed jointly with ABF & ZPMC QA/QC representatives and Caltrans QA Lumley when achievable. International Protective Coatings technical service representative were available for inspections and consultation.

**Summary of Conversations:**

No relevant conversations on this date.

**Comments**

---

---

## SOURCE INSPECTION REPORT

*( Continued Page 2 of 2 )*

---

---

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (858) 699-9549, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Lumley,James	Quality Assurance Inspector
<b>Reviewed By:</b>	Peterson,Art	QA Reviewer

---