

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-008141**Date Inspected:** 08-Aug-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Li Ming Yang
Inspected CWI report: Yes No N/A
Electrode to specification: Yes No N/A
Qualified Welders: Yes No N/A
Approved Drawings: Yes No N/A

CWI Present: Yes No
Rod Oven in Use: Yes No N/A
Weld Procedures Followed: Yes No N/A
Verified Joint Fit-up: Yes No N/A
Approved WPS: Yes No N/A
Delayed / Cancelled: Yes No N/A

Bridge No: 34-0006**Component:** OBG segments**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Steve Hall was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

OBG assembly bay 13

This QA observed ZPMC qualified welding personnel identified as 051359 perform SMAW welding on OBG segment 8CW weld joints identified as SSD22-PP68.5-129~136. ZPMC QC identified as Mr. Wang Xu was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2113-FCM.

This QA observed ZPMC qualified welding personnel identified as 054013 perform SMAW welding on OBG segment 8CW weld joints identified as SSD10A-PP68-140~151. ZPMC QC identified as Mr. Wang Xu was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2113-FCM.

OBG assembly bay 14

This QA observed ZPMC qualified welding personnel identified as 043661 perform SMAW welding on OBG segment 9BE weld joint identified as SEG052A-020. ZPMC QC identified as Mr. Gang Wei was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2214-B-U2-FCM-1.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA observed ZPMC qualified welding personnel identified as 202122 perform FCAW welding on corner assembly for OBG segment 9BW weld joint identified as CA059-003. ZPMC QC identified as Mr. Li Ming Yang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2231-Tc-U4b-F.

This QA observed ZPMC qualified welding personnel identified as 201215 perform FCAW welding on corner assembly for OBG segment 9CW weld joints identified as CSD2-PP78.5-111, 112, 115, 116, 119 and 120. ZPMC QC identified as Mr. Li Ming Yang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2133.

Outside OBG segments 7DW, 7BW, 7EW, 6AW, 6CW, 6CE, 7EE, 7DE, 7CE, 6AE, 7CW, 7BE, 7AW, 6BE, 6BW and 7AE

This QA observed that no significant work was being performed on these segments during the time QA was present.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (15000422372), who represents the Office of Structural Materials for your project.

Inspected By:	Hall,Steven	Quality Assurance Inspector
Reviewed By:	Prue,Erik	QA Reviewer
