

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-009568**Date Inspected:** 05-Oct-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 45**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Chen fu you**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, S.Chandrakumar was present during the times noted above for observations relative to the work being performed.

BAY#14

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA inspector generated an UT report for this date. The members are identified as OBG Segment 9BE. The weld designations reviewed are as follows:

SEG052\*-045.

SMAW welding of weld joint 3G-039 located on PCMK SP772-001 of 10CW welder is identified as 058243. ZPMC QC is identified as Mr. Xu tao. The welding variables recorded by QC appeared to Comply with the WPS-B-P-2213-B-U2a-1.

FCAW welding of weld joint 3G-130 located on PCMK SSD10-PP92 of 10CW welder is identified as 202122. ZPMC QC is identified as Mr. Xu tao. The welding variables recorded by QC appeared to Comply with the WPS-B-T-2233-B-U2-F.

SMAW welding of weld joint 4G-024 located on PCMK SEG051A of 9BW welder is identified as 067829. ZPMC QC is identified as Mr. Xu tao. The welding variables recorded by QC appeared to Comply with the WPS-B-P-2214-Tc-U4b-FCM-1.

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

FCAW welding of weld joint 1G-017 located on PCMK SEG071H of 11DW welder is identified as 0201215. ZPMC QC is identified as Mr. Li wan ning. The welding variables recorded by QC appeared to Comply with the WPS-B-T-2221-B-U2-F.

Visual inspection of following weld joints carried out with ZPMC QC Mr.Xu tao to comply with The WPS-B-T-2233-B-U2-F. the joint no's are  
SSD12-PP94-133.  
SSD11A-PP93-013.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

**Summary of Conversations:**

No Relevant Conversation.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Jim Simonis - 134-7246-3441, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Kumar,Chadra	Quality Assurance Inspector
<b>Reviewed By:</b>	Patterson,Rodney	QA Reviewer

---