

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-011190**Date Inspected:** 25-Dec-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Liu Fawen**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Orthotropic Box Girder (OBG) & Tower Com**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials Quality Assurance Inspector, Sandeep Kumar (QA) was present during the times noted above for observations relative to the work being performed.

BAY 3

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW):

Weld joint # 045 located on Corner Assembly CA3001. Welder is identified as 044824. ZPMC Quality Control (QC) Inspector is identified as Guo Yuan Ting. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2233 – Tc – U4b – F.

Weld joint # 069 located on SEG072E. Welder is identified as 044830. ZPMC Quality Control (QC) Inspector is identified as Guo Yuan Ting. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2233 – Tc – U4b – F.

Shielded Metal Arc Welding (SMAW):

Weld joint # 161 located on Cross Beam CB202G – 044. Welder is identified as 058102. ZPMC Quality Control (QC) Inspector is identified as Guo Yuan Ting. The welding variables recorded by QC appeared to comply with the WPS – B – P – 2113.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Weld joint # 165 located on Cross Beam CB202G – 042. Welder is identified as 057795. ZPMC Quality Control (QC) Inspector is identified as Guo Yuan Ting. The welding variables recorded by QC appeared to comply with the WPS – B – P – 2113.

BAY 5

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW):

Weld joint # 003 located on Bike Path BK001 – 045. Welder is identified as 066734. ZPMC Quality Control (QC) Inspector is identified as Wang Liyang. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2231 – Tc – U4c – F.

Weld joint # 002 located on Bike Path BK001 – 043. Welder is identified as 067601. ZPMC Quality Control (QC) Inspector is identified as Wang Liyang. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2231 – Tc – U4c – F.

Weld joint # 004 located on Bike Path BK001 – 044. Welder is identified as 204342. ZPMC Quality Control (QC) Inspector is identified as Wang Liyang. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2231 – Tc – U4c – F.

Weld joint # 002 located on Bike Path BK001 – 047. Welder is identified as 217185. ZPMC Quality Control (QC) Inspector is identified as Wang Liyang. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2231 – Tc – U4c – F.

BAY 6

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No. 004929

Ultrasonic Testing (UT)

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member is identified as TOWER Component. The weld designations reviewed are as follows:

WEST TOWER LIFT 2

1. WD1 – A305 – 77M – 1 – 1; 2; 7; 8; 9; 10 – (A/B)

BAY 7

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW):

Weld joint # 005 located on Traveler Rail 22TR4 – 004. Welder is identified as 067877. ZPMC Quality Control (QC) Inspector is identified as Zhou Jie. The welding variables recorded by QC appeared to comply with the WPS

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

– B – T – 2232 – Tc – U5 – F.

Weld joint # 007 located on Traveler Rail 22TR1 – 001. Welder is identified as 200676. ZPMC Quality Control (QC) Inspector is identified as Zhou Jie. The welding variables recorded by QC appeared to comply with the WPS

– B – T – 2232 – Tc – U5 – F.

BAY 8

This QA Inspector observed the following work in progress:

Flux Core Arc Welding (FCAW):

Weld joint # 021 located on Floor Beam FB3057 – 056. Welder is identified as 054459. ZPMC Quality Control (QC) Inspector is identified as Zhang Qiao. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2232 – Tc – U4b – F.

Weld joint # 021 located on Floor Beam FB3057 – 055. Welder is identified as 215082. ZPMC Quality Control (QC) Inspector is identified as Zhang Qiao. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2232 – Tc – U4b – F.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No Relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang - 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Sandeep	Quality Assurance Inspector
Reviewed By:	Hall,Steven	QA Reviewer
