

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/Ala Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-012513**Date Inspected:** 23-Feb-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance Inspector (QA Inspector) George Goulet was present during the times noted above for observations relative to the work being performed.

Bay 10

This QA Inspector randomly observed the following work in progress in Bay 10:

SMAW welding of weld joint SSD1-TL5-1B-F-52A located inside PCMK south tower, lift 5, skins D/E corner. Welder was identified as 050289. ZPMC QC was identified as Gong Liang Zhu (QC1). The welding variables recorded by QC1 appeared to comply with WPS-B-T-3211-TC-U4b-1. Also present at this location and appearing to be monitoring the welding related operations was ABF Representative Yang Ye Heng.

Heavy Dock

This QA Inspector randomly observed the following work in progress on the Heavy Dock:

FCAW welding of weld joint SSD1-SA17-80 located outside PCMK south tower, lift 1 base, skin C, shear plate stiffener. Welder was identified as 050598. ZPMC QC was identified as CWI You Qi Guo (QC2). Assisting QC2 at this location and appearing to be monitoring the welding and recording data was ZPMC Qiu Wen, who was not a CWI. The welding variables recorded by QC2's assistant appeared to comply with WPS-B-T-2333-TC-P4-F.

The tower access elevator was not manned after 2115 hours and it appeared that no work was being performed at

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

the lift 1/ lift 2 joints of the east and south towers. West tower, lift 2 was suspended vertically from the ZPMC 1600 ton floating crane, approximately 10M over the foot of the heavy dock.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No significant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Skyler Guest, 150-0042-2360, who represents the Office of Structural Materials for your project.

Inspected By:	Goulet,George	Quality Assurance Inspector
Reviewed By:	Dawson,Paul	QA Reviewer
