

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014459**Date Inspected:** 29-May-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhou Cheng.**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

Outside Yard:

CB11, CB12, CB13 & CB16:

This QA Inspector observed that no significant work was being performed on the above mentioned CB's at the time when this QA was present.

CB14:

This QA Inspector observed the following work in progress:

Repair welding of weld joint nos: FB204-043-053 & FB205-043-029. Welder was identified as 044844. Welding process was identified as Shielded Metal Arc Welding (SMAW). ZPMC Quality Control (QC) is identified as Zhan Hal Feng. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-345-SMAW-4G(4F)-Repair [welding repair report (WRR) no: B-WR13022 Rev-0 & B-WR13049 Rev-0].

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Trial Assembly:

CB7, CB8, CB9 & CB10:

This QA Inspector observed that no significant work was being performed on this CB at the time when this QA was present.

Bay 14:

This QA Inspector observed the following work in progress:

SMAW of weld joints SEG3005L-001 (for OBG SEG 12 BW). Welders are identified as 037748 & 037840. ZPMC QC is identified as Zhong Yang Gang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-P-2214-B-U2-FCM-1.

Flux Cored Arc Welding (FCAW) of weld joints SEG3006B-PP117-134 & 135 (for OBG SEG 12 CW). Welder is identified as 67949. ZPMC QC is identified as Zhong Yang Gang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-T-2233-TC-U4b-F.

Bay 19:

This QA Inspector observed the following work in progress:

Repair welding (buttering) done at the ID of the suspender rod holes of OBG component Suspender Bracket SB48E. Welder is identified as 062757. Welding process was identified as SMAW. ZPMC QC is identified as Zhong Cheng. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-345-SMAW-1G(1F)-Repair [critical welding report (CWR) no: B-CWR1572 Rev-0 Dt: 05/21/10]. Refer attached photos for further details.

Notification No: 005852.

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC QC personnel. This QA Inspector has generated MT report for this date. The member(s) are identified as OBG component – Bottom Panel. The weld designations reviewed are as follows:

1) BP3017-001-044, 045, 046, 014, 015, 016, 017, 020 & 021.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372., who represents the Office of Structural Materials for your project.

Inspected By: Wadkar,Sailesh

Quality Assurance Inspector

Reviewed By: Hall,Steven

QA Reviewer