

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014586**Date Inspected:** 01-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** An Qing Xiang.**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Shailesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

BAY 11

This QA Inspector performed randomly Visual Inspection and Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL- 6028 (MT) report for this date. The member is identified as Shear Plate A29. The weld designations reviewed are as follows.

ED1-A29A/B-27, 28, 31, 32, 57, 61, 62, 67, 69, 73

NDT Notification No-005873

This QA Inspector observed the following work in progress:

BAY 11:**SMAW Process:**

This QA Inspector observed ZPMC qualified welding personnel identified as 202100, 251194. Perform Shielded Metal Arc Welding (SMAW) on Tower Strut. Joint identified as ND1-STSA4-10-119M-2-51, 57, ZPMC QC Identified as Liu Dao Feng, The welding parameters as measured using QC's calibrated instrument appeared to be

WELDING INSPECTION REPORT

(Continued Page 2 of 4)

in general compliance with WPS-B-T-2112.

This QA Inspector observed ZPMC qualified welding personnel identified as 202100, 251194. Perform Shielded Metal Arc Welding (SMAW) on Tower Strut. Joint identified as ND1-STSA4-10-119M-2-52, 58, ZPMC QC Identified as Liu Dao Feng, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-4113-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 040614, 040675. Perform Shielded Metal Arc Welding (SMAW) on Tower Strut. Joint identified as ND1-STSA4-10-119M-1-44, 42, ZPMC QC Identified as Liu Dao Feng, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-4113-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 040614, 040675. Perform Shielded Metal Arc Welding (SMAW) on Tower Strut. Joint identified as ND1-STSA4-10-119M-1-43, 41, ZPMC QC Identified as Liu Dao Feng, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2113.

This QA Inspector observed ZPMC qualified welding personnel identified as 040655, Perform Shielded Metal Arc Welding (SMAW) on Tower Strut. Joint identified as ED1-STSA4-10-119M-2-52, 58, ZPMC QC Identified as Liu Dao Feng, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-4113-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 046769. Perform Shielded Metal Arc Welding (SMAW) on Tower Strut. Joint identified as ED1-STSA4-10-119M-2-51, 57, ZPMC QC Identified as Liu Dao Feng, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2113.

Repair Welding

This QA Inspector observed ZPMC qualified welding personnel identified as 041271, Perform Shielded Metal Arc Welding (SMAW) on Angle Connect Plate. Joint identified as ED1-SA4-69-119M-7-1A/B. ZPMC QC Identified as Fu Wei Min, with Critical welding repair report CWR-T-CWR631, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-485-SMAW-1G (1F)FCM-Repair-1. For more information see below attach photo number 1.

SMAW Process

This QA Inspector observed ZPMC qualified welding personnel identified as 044551, Perform Shielded Metal Arc Welding (SMAW) on Interior Splice Plate. Joint identified as ESD1-SPSA5-2-1B. ZPMC QC Identified as Shao Hai Lang, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3211-Tc-U5b-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 040619, Perform Shielded Metal Arc Welding (SMAW) on West Tower lift 5 Grillage Plate. Joint identified as WSD1-TL5-4B/K-11A. ZPMC QC Identified as Libin, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3213-B-U3b.

WELDING INSPECTION REPORT

(Continued Page 3 of 4)

FCAW Process:

This QA Inspector observed ZPMC qualified welding personnel identified as 040725, 053316, 049541, 040759, Perform Flux Core Arc Welding (FCAW) on Shear plate bearing stiffener weld. Joint identified as WD1-A25B/E-90, 79, 78, 67. ZPMC QC Identified as Xu Jie. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-2331-Tc-P4-F.

BAY 10

SMAW Process


This QA Inspector observed ZPMC qualified welding personnel identified as 052930, Perform Shielded Metal Arc Welding (SMAW) on Interior Splice plate. Joint identified as SSD1-SPSA5-19-1B. ZPMC QC Identified as Yu Zhi Lai, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3211-Tc-U5b-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 050289, Perform Shielded Metal Arc Welding (SMAW) on Interior Splice plate. Joint identified as SSD1-SPSA5-16-3A. ZPMC QC Identified as Yu Zhi Lai, The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-B-T-3211-Tc-U5b-1.

Repair Welding, FCAW Process:

This QA Inspector observed ZPMC qualified welding personnel identified as 040533, Perform Flux Core Arc Welding (FCAW) on North tower lift 4 C/D corner Diagonal Plate. Joint identified as NSTL4-3D/L-41. ZPMC QC Identified as Lu Wei Chao, with Temporary welding repair report. The welding parameters as measured using QC's calibrated instrument appeared to be in general compliance with WPS-345-FCAW-3G (3F)-Repair. For more information see below attach photo number 2.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.



Summary of Conversations:

WELDING INSPECTION REPORT

(Continued Page 4 of 4)

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Skyler Guest phone: 15000422360, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Shailesh	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
