

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014638**Date Inspected:** 10-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	Xu Xian Ping	CWI Present:	Yes	No
Inspected CWI report:	Yes No N/A	Rod Oven in Use:	Yes No N/A	
Electrode to specification:	Yes No N/A	Weld Procedures Followed:	Yes No N/A	
Qualified Welders:	Yes No N/A	Verified Joint Fit-up:	Yes No N/A	
Approved Drawings:	Yes No N/A	Approved WPS:	Yes No N/A	
		Delayed / Cancelled:	Yes No N/A	
Bridge No:	34-0006	Component:	OBG	

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

Bay 1: CB15.

This QA Inspector observed that no significant work was being performed on the above mentioned CB at the time when this QA was present.

Bay 8: CB17.

This QA Inspector observed the following work in progress:

Flux Cored Arc Welding (FCAW) of weld joints CB3001A-017-020. Welder is identified as 054460. ZPMC QC is identified as Feng Ya Jun. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-T-2232-TC-U4b-F.

FCAW of lifting lugs with Bottom panel. Welder is identified as 054460. ZPMC QC is identified as Feng Ya Jun. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-T-2231-B-U2-F.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Trial Assembly:

CB9 & CB10:

This QA Inspector observed that no significant work was being performed on the above mentioned CB's at the time when this QA was present.

Outside Yard:

CB13:

This QA Inspector observed ABF personnel doing MT and UT of the welds of this CB. This QA Inspector did random visual inspection & the welds areas identified as not to be complying with the contract documents were marked in question for the Contractors QC to inspect and evaluate.

CB11, CB12, CB14 & CB16:

This QA Inspector observed that no significant work was being performed on the above mentioned CB's at the time when this QA was present.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372., who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By:	Wadkar,Sailesh	Quality Assurance Inspector
----------------------	----------------	-----------------------------

Reviewed By:	Hall,Steven	QA Reviewer
---------------------	-------------	-------------
