

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-020368**Date Inspected:** 30-Aug-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Liu Hua Jie**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment Assembly**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Ramesh Gade, was present during the times noted above for observations relative to the work being performed.

This QA Inspector performed the following work:

OBG Segment 9AE

This QA inspector performed Magnetic Particle Testing (MT) approximately 15% of the area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated MT report for this date. The member is identified as 9AE Drain plate welds as per ZPMC notification # 06527 item # 1.

The weld designations reviewed are as follows:

OBE9D-062, 063, 046 and 047

OBG Segment 9CE

This QA inspector performed Magnetic Particle Testing (MT) approximately 15% of the area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated MT report for this date. The member is identified as Service Platform Connection Bracket welds as per ZPMC notification # 06529 item # 1.

---

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

The weld designations reviewed are as follows:

OBE9B-011, 024, 025 and 034

OBG Segment 9AW

This QA inspector performed Ultrasonic Testing (UT) approximately 10% of the area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an UT report for this date. The member is identified as Counterweight & Cross beam side SP to CA long seam heat straightened area as per ZPMC notification # 06527 item # 3.

The weld designations reviewed are as follows:

SEG049A-001 and 010

OBG Segment 9DW-9EW

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a data sheet that Caltrans QA generates after performing a joint inspection. The members are identified as the Counterweight connection plate weld.

ZPMC notification # 06531

The weld designations reviewed are as follows:

OBW9K-013 and 015

**Summary of Conversations:**

No relevant conversations reported on this date.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (+86)15000 42 2372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Gade,Ramesh	Quality Assurance Inspector
----------------------	-------------	-----------------------------

---

<b>Reviewed By:</b>	McClendon,Timothy	QA Reviewer
---------------------	-------------------	-------------