

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-022193**Date Inspected:** 27-Mar-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See Below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

CWI Inspector: Mr. Lv Li Qing

On this date CALTRANS OSM Quality Assurance (QA) Inspector, Mr. Paul Dawson, arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai China, for the purpose of monitoring welding and fabrication of the San Francisco / Oakland Bay Bridge (SFOBB) components. This QA Inspector observed the following:

**OBG Bay 14**

This QA Inspector observed ZPMC welder Mr. Zhu Mingsong, stencil 204339 used shielded metal arc welding procedure WPS-345-SMAW-2G(2F)-FCM-Repair to make a weld repair of magnetic particle rejections to OBG segment 13BE weld SEG3009F-236. This QA Inspector measured a welding current of approximately 170 amperes (amps), the base materials had been preheated with a torch and Mr. Zhu Mingsong appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.

This QA Inspector observed ZPMC welder Mr. Wang Li, stencil 044772 used shielded metal arc welding procedure specification WPS-B-P-2214-T-U4B-FCM-1 to make OBG segment 14E weld SEG3019U-001. This QA Inspector observed a welding current of approximately 180 amps, the base material had been preheated with electric heaters and Mr. Wang Li appeared to be certified to make this weld. Items observed on this date appeared

---

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 3 )

---

---

to generally comply with applicable contract documents.

This QA Inspector observed ZPMC welder Mr. Wu Hai Jun, stencil 201087 used shielded metal arc welding procedure WPS-B-P-2214-TC-U4B-FCM-1 to make OBG segment 14E weld SEG3019BB-023. This QA Inspector observed a welding current of approximately 185 amps the base materials were preheated with electrical heaters and Mr. Wu Hai Jun appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.

This QA Inspector observed ZPMC welder Mr. Yin Xiao Kai, stencil 050232 used shielded metal arc welding procedure WPS-B-P-2214-TC-U4B-FCM-1 to make OBG segment 14E weld SEG3019BB-067. This QA Inspector observed a welding current of approximately 180 amps the base materials were preheated with electrical heaters and Mr. Yin Xiao Kai appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.

This QA Inspector observed ZPMC welder Mr. Wang Zhengbin, stencil 216086 used shielded metal arc welding procedure WPS-B-P-2214-TC-U4B-FCM-1 to make OBG segment 14E weld SEG3019BB-089. This QA Inspector observed a welding current of approximately 180 amps the base materials were preheated with electrical heaters and Mr. Wang Zhengbin appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.

This QA Inspector observed ZPMC welder Mr. Yang Yunfeng, stencil 215553 used shielded metal arc welding procedure WPS-B-P-2214-TC-U4B-FCM-1 to make OBG segment 14E weld SEG3019BB-133. This QA Inspector observed a welding current of approximately 185 amps the base materials were preheated with electrical heaters and Mr. Yang Yunfeng appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.

This QA Inspector observed ZPMC welder Mr. Zhao Guanglin, stencil 044779 used shielded metal arc welding procedure WPS-B-P-2214-TC-U4B-FCM-1 to make OBG segment 14E weld SEG3019BB-155. This QA Inspector observed a welding current of approximately 180 amps the base materials were preheated with electrical heaters and Mr. Zhao Guanglin appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.

This QA Inspector observed ZPMC welder Mr. Kuai Wenshan, stencil 054013 used shielded metal arc welding procedure WPS-B-P-2214-TC-U4B-FCM-1 to make OBG segment 14E weld SEG3019BB-177. This QA Inspector observed a welding current of approximately 190 amps the base materials were preheated with electrical heaters and Mr. Kuai Wenshan appeared to be certified to make this weld. Items observed on this date appeared to generally comply with applicable contract documents.

---

# WELDING INSPECTION REPORT

( Continued Page 3 of 3 )

---



## Summary of Conversations:

See Above.

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey +8615000026784, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Dawson,Paul	Quality Assurance Inspector
<b>Reviewed By:</b>	Riley,Ken	QA Reviewer

---