

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-026376**Date Inspected:** 19-Mar-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC) Changxing Island **Location:** Shanghai, China**CWI Name:** Lv Li Qing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Vikram Singh was present during the times noted above for observations relative to the work being performed at ZPMC.

OBG Bay 14

WELDING

This QA Inspector randomly observed the following work in progress:

Flux Cored Arc Welding (FCAW)

This QA Inspector observed the welding operation per the FCAW process on a weld joint identified as SA3232A-033 located on the OBG Segment 14W. The welder is identified as 066421. ZPMC Quality Control (QC) is identified as Mr. Zhan Lin. The welding variables recorded by QC appeared to comply with WPS-B-T-2232-ESAB.

This QA Inspector observed the welding operation per the FCAW process on a weld joint identified as Seg3020AJ-344 located on side plate I-rib of the OBG Segment 14W. The welder is identified as 067949. ZPMC Quality Control (QC) is identified as Mr. Zhan Lin. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA Inspector observed the welding operation per the FCAW process on a weld joint identified as Seg3020AJ-225 located on side plate I-rib of the OBG Segment 14W. The welder is identified as 067949. ZPMC Quality Control (QC) is identified as Mr. Zhan Lin. The welding variables recorded by QC appeared to comply with WPS-B-T-2132-ESAB.

Shielded Metal Arc Welding (SMAW)

This QA Inspector observed the welding operation per the SMAW process on a weld joint identified as SEG3015G-009 located on the OBG Segment 13CW. The welder is identified as 067993. ZPMC Quality Control (QC) is identified as Mr. Zhan Lin. The welding variables recorded by QC appeared to comply with WPS-B-P-2213-B-U2-FCM-1.

This QA Inspector observed the welding operation per the SMAW process on a weld joint identified as SA3231C-001-118 located on the OBG Segment 13BW. The welder is identified as 067876. ZPMC Quality Control (QC) is identified as Mr. Zhan Lin. The welding variables recorded by QC appeared to comply with WPS-SMAW-3G (3F)-FCM-Repair and B-WR20439.

This QA Inspector observed the welding operation per the SMAW process on a weld joint identified as Seg3020AZ-195 located on side plate I-rib of the OBG Segment 14W. The welder is identified as 067765. ZPMC Quality Control (QC) is identified as Mr. Zhan Lin. The welding variables recorded by QC appeared to comply with WPS-B-P-2213-Tc-U4b-FCM-1


This QA Inspector observed the welding operation per the SMAW process on a weld joint identified as DP3218-001-058 located on the OBG Segment 13BW. The welder is identified as 067876. ZPMC Quality Control (QC) is identified as Mr. Zhan Lin. The welding variables recorded by QC appeared to comply with WPS-SMAW-3G (3F)-FCM-Repair and B-WR20439.

This QA Inspector observed the welding operation per the SMAW process on a weld joint identified as SA3231C-001-008 located on the OBG Segment 13BW. The welder is identified as 067829. ZPMC Quality Control (QC) is identified as Mr. Zhan Lin. The welding variables recorded by QC appeared to comply with WPS-B-P-2214-B-U2-FCM-1. For more details please see attached photo below:

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

No relevant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Singh, Vikram	Quality Assurance Inspector
Reviewed By:	Patterson, Rodney	QA Reviewer
