

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024771**Date Inspected:** 08-Jun-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Kelly Leavitt, was present during the times noted above for random observations relative to the work being performed.

Trial Assembly

This QA Inspector observed the following work in progress for Trial Assembly.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is identified as Wang Xiang Pin.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

Components; OBG 13BE (see photo)

PCMK: SEG3009S

Weld No: 058

Welder: 066746

WPS-B-T-2232-ESAB

Components; OBG 13BE

PCMK: SEG3009S

Weld No: 001

Welder: 066746

WPS-B-T-2232-ESAB

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA Inspector observed the following work in progress for Trial Assembly.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Wang Xiang Pin.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

Components; OBG 13BE

PCMK: OBE13B


Weld No: 001

Welder: 044772

Repair No, B-CWR2992

WPS-345-SMAW-4G(4F)-FCM-Repair-1

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

“No relevant conversations.”

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey 1500026784, who represents the Office of Structural Materials for your project.

Inspected By: Leavitt, Kelly

Quality Assurance Inspector

Reviewed By: Riley, Ken

QA Reviewer