

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024813**Date Inspected:** 28-Jun-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See Below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

Summary of Items Observed: On this date Caltrans OSM Quality Assurance (QA) Inspector, Mike Hasler was present during the times noted above for observations and testing relative to the work being performed.

Bay 19

This QA inspector performed a random observation for the OBG. During the observation performed it was noted ZPMC was in process of grinding exterior welds and surfaces on bike path assembly BK25A and interior welds and surfaces on bike path assembly BK23A. ABF CWI inspector Peng Wen Jun was present at this time of this observation and informed this QA inspector of the work that is in process. It was stated that ZPMC would not be performing welding in Bay 19 during this work shift.

Bay 16

This QA inspector performed a random observation for the OBG. During the observation performed it was noted ZPMC was in process of grinding interior welds and surfaces on W2 & E2 Steel Barriers.

This QA inspector observed ZPMC personnel performing material preparation and fit-up alignment for the OBG Bike path handrail assembly BKR-FS-28 & 13.

This QA inspector observed ZPMC personnel grinding weld bevel material preparation and fit-up alignment for the OBG Bike path cantilever truss assembly (BKSA8A, BKSA9A, BKSA10A, BKSA10B) for PP5.5. ABF QC Gao Zhen Kun was present at this time of this observation and informed this QA inspector of the work that is in process and identified Peng Wen Jun as the CWI. It was stated that ZPMC would not be performing welding in Bay 19 during this work shift.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

“As noted within the contents of this report.”

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact James Devey 15000026784, who represents the Office of Structural Materials for your project.

Inspected By:	Hasler, Mike	Quality Assurance Inspector
----------------------	--------------	-----------------------------

Reviewed By:	Riley, Ken	QA Reviewer
---------------------	------------	-------------