

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-025061**Date Inspected:** 03-Jul-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** An Qing Xiang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the Self-Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

**BLAST SHOP 4, OBG 13AW**

This QA Inspector performed Blast inspection on base metal, fillet welds and complete joint penetration (CJP) welds from panel point (PP) 119+1500 to PP 120.5 on internal surface of floor beam, side panel and bottom panel of OBG segment 13AW at cable side section. During inspection, several non conforming discontinuities such as weld spatter, deep gouges, arc strikes and improper temporary attachment removal were observed. These areas were marked up for repair. All information regarding this marked on weld map and submitted to Lead QA Inspector. See attached photos for additional information.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---



## Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang : 15000422372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Gaikwad,Umesh	Quality Assurance Inspector
<b>Reviewed By:</b>	Peterson,Art	QA Reviewer

---