

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002545**Date Inspected:** 22-May-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1430**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2230**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

<b>CWI Name:</b>	N/A	<b>CWI Present:</b>	Yes	No
<b>Inspected CWI report:</b>	Yes No N/A	<b>Rod Oven in Use:</b>	Yes No N/A	
<b>Electrode to specification:</b>	Yes No N/A	<b>Weld Procedures Followed:</b>	Yes No N/A	
<b>Qualified Welders:</b>	Yes No N/A	<b>Verified Joint Fit-up:</b>	Yes No N/A	
<b>Approved Drawings:</b>	Yes No N/A	<b>Approved WPS:</b>	Yes No N/A	
		<b>Delayed / Cancelled:</b>	Yes No N/A	
<b>Bridge No:</b>	34-0006	<b>Component:</b>	Deck Panels/OBG	

**Summary of Items Observed:**

On this date, Caltrans Office of Structural Materials (OSM) Quality Assurance (QA) Inspector Edward Leach was present to randomly observe and document the welding and Quality Control (QC) functions performed by ZPMC personnel relative to the fabrication of SAS Superstructure project. While on site, the QA Inspector noted the following work.

**OBG-Bay 1**

The QA Inspector completed initial visual testing (VT) for the closed rib partial joint penetration (PJP) welds for deck panel designation DP594-001, welds 1 through 10 and recorded Y locations, defect type and defect lengths onto a Caltrans inspection report.

Later in the shift the QA Inspector started initial VT for closed rib deck panel designation DP584-001. The QA Inspector completed VT for weld 1 and weld 6 only as of the end of the shift. The remaining VT was later completed by third shift QA personnel.

The following digital images below detail DP594-001 as a five rib deck panel and the QA markings that were written at the beginning of each Y location above each weld.

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---



## Summary of Conversations:

No relevant conversations this date.

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Leach,Ed	Quality Assurance Inspector
<b>Reviewed By:</b>	Carreon,Albert	QA Reviewer

---