

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002912**Date Inspected:** 15-Jun-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 630**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1430**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Wang Sei Fa**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Deck Panel Repairs**Summary of Items Observed:**

On this date CALTRANS OSM Quality Assurance (QA) Inspector was present during the times noted above for observations relative to the work being performed.

Bay 3 – New Tower Building

This QA Inspector randomly observed ZPMC welding and quality control personnel performing inspection, grinding, and Flux Core Arc Welding (FCAW) repairs of Orthotropic Box Girder (OBG) deck panel Partial Joint Penetration (PJP) welds. The deck panels in repair process are designated as: DP028-001, DP026-002, DP042-001.

In process deck panel repairs appear to be progressing in compliance with Caltrans Engineer Approved Repair Procedure.

The deck panels located in Tower Shop Bay #3 are designated as:

DP042-001 DP028-001 DP032-001 DP080-001 DP055-001 DP071-001
DP049-001 DP077-001 DP065-001 DP005-001 DP006-001 DP029-001
DP067-001 DP078-001 DP026-002 DP030-002 DP075-001 DP027-001
DP050-001 DP015-001 DP001-001 DP052-001 DP054-001 DP042-002
DP025-001 DP072-001 DP070-001 DP003-001 DP031-001 DP068-001
DP030-001 DP043-001 DP037-001 DP051-001 DP074-001 DP038-001
DP026-001


WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Visual Testing Before Repair

This QA Inspector performed an initial visual confirmation of the extent of rejectable indications contained in deck panel designated as DP078-001. This visual confirmation was performed in conjunction with ABF representative Warren Buehler and ZPMC representative Wang Sei Fa.

This QA Inspector reviewed the contract files and tracking logs for the Magnetic Particle Testing (MT), Ultrasonic Testing (UT), Welding Procedure Specifications (WPS), Procedure Qualification Records (PQR), and QC Inspector records for the deck panel repairs to date.



Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By: Clifford, William

Quality Assurance Inspector

Reviewed By: Cuellar, Robert

QA Reviewer