

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-003080**Date Inspected:** 05-Jun-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2230**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Wei Sei Fa**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Deck Panels**Summary of Items Observed:**

On this date, Caltrans Office of Structural Materials (OSM) Quality Assurance (QA) Inspector Edward Leach was present to randomly observe and document the welding and Quality Control (QC) functions performed by ZPMC personnel relative to the fabrication of SAS Superstructure project. While on site, the QA Inspector noted the following work.

Bay 3 – New Tower Building

The QA Inspector randomly observed ZPMC welding and QC personnel performing inspection, grinding, and Flux Core Arc Welding (FCAW) repairs of Orthotropic Box Girder (OBG) deck panel Partial Joint Penetration (PJP) welds. During initial observations it was noted that thirty-one (31ea) deck panels are inside the shop. The deck panels in repair process are designated as: DP052-001, DP051-001, DP029-001 & DP003-001. The QA Inspector documented areas of repair for DP052-001, weld designations 001 through 010.

Magnetic Particle Testing

The QA Inspector performed Magnetic Particle Testing (MT) of approximately 15% of the QC final MT completed deck panel repairs on deck panel designations DP049-001 and DP050-001. This QA Inspector generated a TL-6028 MT report on this date. The weld designations where the MT was performed on both deck panels is 001 & 010.

The QA Inspector reviewed the contract files and tracking logs for the Magnetic Particle Testing (MT), Ultrasonic Testing (UT), Welding Procedure Specifications (WPS), Procedure Qualification Records (PQR), and QC Inspector records for the deck panel repairs to date.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

No relevant conversations this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Leach,Ed	Quality Assurance Inspector
----------------------	----------	-----------------------------

Reviewed By:	Carreon,Albert	QA Reviewer
---------------------	----------------	-------------