

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 13.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-003752**Date Inspected:** 03-Sep-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Oregon Iron Works Clackamas, Or.**Location:** Clackamas, Oregon

CWI Name:	Mike Gregson		
Inspected CWI report:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A

CWI Present:	Yes	No	
Rod Oven in Use:	Yes	No	N/A
Weld Procedures Followed:	Yes	No	N/A
Verified Joint Fit-up:	Yes	No	N/A
Approved WPS:	Yes	No	N/A
Delayed / Cancelled:	Yes	No	N/A

Bridge No: 34-0006**Component:** Hinge K Components**Summary of Items Observed:**

On this date, Caltrans Quality Assurance (QA) Inspector Mr. Danny C. White (B89) was present at Oregon Iron Works (OIW) for the purpose of monitoring fabrication and welding operations of the Hinge K Pipe Beam at the OIW fabrication and welding shop in Clackamas, Oregon.

The QA Inspector performed random observations in the fabrication shop in bay #1 and observed Mr. Scott Jones was performing machining operations on the base-plate component marked as A109-1D for this job.

Also in bay #1 the QA Inspector observed an OIW machinist helper utilized an pneumatic tool with a buffer wheel to remove burrs and sharp edges from grout grooves, holes and edges of base plate A110-4. Please see photo below for additional information. It is noted that Mr. Jones utilized protective material while handling the base plate at the contact areas between the lifting chains and the base plate.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

No pertinent conversations occurred this day.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ryan Smith, (858) 232-6799, who represents the Office of Structural Materials for your project.

Inspected By:	White,Danny	Quality Assurance Inspector
----------------------	-------------	-----------------------------

Reviewed By:	Wright,Mark	QA Reviewer
---------------------	-------------	-------------