

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-004593**Date Inspected:** 06-Nov-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 630**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1430**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Wang Sei Fa**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower Components**Summary of Items Observed:**

On this date CALTRANS OSM Quality Assurance (QA) Inspector was present during the times noted above for observations relative to the work being performed.

Bay 3 – New Tower Shop**Visual Testing After Repair**

This QA performed Visual Testing (VT) of completed deck panel repairs. The weld repairs were found visually acceptable per Caltrans Engineer Approved Repair Procedure. The deck panel designation number is as follows: DP274-001, DP139-001, and DP409-001.

Visual Testing Before Repair

This QA Inspector performed an initial visual confirmation of the extent of rejectable indications contained in deck panel designated as DP493-001, DP088-001, and DP495-001. This visual confirmation was performed in conjunction with ABF representative Kevin Chen and ZPMC representative Sun Bo.

Bay 2 – New Tower Shop**Magnetic Particle Testing**

This QA Inspector performed Magnetic Particle Testing (MT) of approximately 25% of the area previously tested by ZPMC MT personnel. This QA Inspector generated a TL-6028 MT report on this date. The weld designation numbers is as follows: WSD1-SA225A/H-61A.

Bay 4 – OBG Sub Assembly

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Magnetic Particle Testing

This QA Inspector performed Magnetic Particle Testing (MT) of approximately 25% of the area previously tested by ZPMC MT personnel. This QA Inspector generated a TL-6028 MT report on this date. The weld designation numbers is as follows: SP488-001, SP540-001, and SP343-001.

Tracking and Log Book

This QA Inspector reviewed the contract files and tracking logs for the Magnetic Particle Testing (MT), Ultrasonic Testing (UT), Welding Procedure Specifications (WPS), Procedure Qualification Records (PQR), and QC Inspector records for the deck panel repairs to date.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Josh Ishibashi, (858) 232-6799, who represents the Office of Structural Materials for your project.

Inspected By:	Clifford,William	Quality Assurance Inspector
----------------------	------------------	-----------------------------

Reviewed By:	Cuellar,Robert	QA Reviewer
---------------------	----------------	-------------