

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-005432**Date Inspected:** 12-Feb-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1500**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Sha Zhi**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG segments**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Steve Hall was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

OBG outside assembly (OBG segment 3BE)

This QA observed ZPMC qualified welding personnel identified as Mr. Jin Chengmao (048551) perform FCAW welding on weld joints identified as SSD19-10~47. ZPMC QC identified as Mr. Wang Wei Ming was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2133.

This QA observed ZPMC qualified welding personnel identified as Mr. Ge Tao (067765) perform SMAW welding on weld joints identified as SSD19-11~14. ZPMC QC identified as Mr. Wang Wei Ming was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2112 and WPS-B-T-2114.

OBG outside assembly (OBG segment 3AE)

This QA performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA generated a UT report for this date. The members are identified as OBG segment 3AE floor beam subassemblies. The weld designations are as follows:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

FB026-01-122, FB026-01-100, FB026-01-081, FB026-01-080, FB003-15-001 and FB014-06-020.

This QA observed ZPMC personnel installing diagonal bracing in corner assembly @ PP20.5.

OBG outside assembly (OBG segment (4AE)

No significant work was being performed on this segment while QA was present.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

Only general conversation was held between QC and QA concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Hall,Steven	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
