

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-007537**Date Inspected:** 23-Jun-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	Ti Jia			CWI Present:	Yes	No	
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A
Bridge No:	34-0006			Component:	OBG & TOWER components		

Summary of Items Observed:

On this date CALTRANS OSM Quality Assurance (QA) Inspector, Dilip Chakrabarti was present during the times noted above for observations relative to the work being performed.

OBG Trial Assembly Area

This QA Inspector randomly observed the following work in progress:

FCAW Process:

Welding of Diaphragm LB 3W located on between PP22 & PP23. Welder is identified as 220063 & 220068. ZPMC QC is identified as Pan Wen Long. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132.

Bay# 11-Tower Assembly

This QA Inspector randomly observed the following work in progress:

SAW Process:

Welding of weld joint# 8B/2 located on PCMK WSD1 FESA4-4 A/F. Welder is identified as 202756. ZPMC QC is identified as Zhan Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2221-B-U3C-S-2.

Welding of weld joint# 12B & 17B located on PCMK WSD1 FESA4-4 A/F. Welder is identified as 044558. ZPMC QC is identified as Zhan Bo. The welding variables recorded by QC appeared to comply with the specified

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

WPS no. B-T-2221-B-U3C-S-2.

Welding of weld joint# 22B located on PCMK WSD1 FESA4-4 A/F. Welder is identified as 040634. ZPMC QC is identified as Zhan Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2221-B-U3C-S-2.

Unless otherwise noted, all work observed on this date appeared to be generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversation

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Chakrabarti,Dilip Kumar	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
