

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-007645**Date Inspected:** 18-Jun-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Zhi Jiang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Hiranch Patel, was present during the times noted above for observations relative to the work being performed.

Bay#2 Segment 1AAE

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member is identified as OBG Segment 1AAE welds. The weld designations reviewed are as follows:

-(Seg2E-362, 320)

-(Seg2C-127)

Bay#2- Segment 1AAW

This QA inspector witnessed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel of Segment 1AAW, seg1E stiffeners weld removal areas. ZPMC QC-CWI Li Zhi Jiang and ABFJV Wang Wen Bin were present during observation. The member is identified as Segment 1AAW. The weld designations reviewed are as follows:

-(Seg1E-164, 254, Seg1C-026) Location-A-26

Bay #2, Segment 1AAE

This QA inspector observed the following work in progress:

SMAW welding of weld joint base metal repair of weld location Seg2E-334, Seg2F-026, Seg2D-088 located on

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

A-41 on Segment 1AAE. Welder is identified as 206358 (3G). ZPMC QC-CWI is identified as Li Zhi Jiang . The welding variables recorded by QC appeared to comply with the Applicable WPS.

FCAW welding of weld joint Seg2E-045, 046, Seg2F-003, 004 located A-00 on Segment 1AAE. Welder is identified as 048433 (3G). ZPMC QC-CWI is identified as Li Zhi Jiang . The welding variables recorded by QC appeared to comply with the Applicable WPS.

FCAW welding of weld joint Seg2E-347, 305, Seg2D-130 located A-13 on Segment 1AAE. Welder is identified as 045203 (3G). ZPMC QC-CWI is identified as Li Zhi Jiang . The welding variables recorded by QC appeared to comply with the Applicable WPS.

SMAW welding of weld joint base metal repair of weld location Seg2E-124, Seg2F-023, Seg2D-004 located on A-00 on Segment 1AAE. Welder is identified as 206358 (3G). ZPMC QC-CWI is identified as Li Zhi Jiang . The welding variables recorded by QC appeared to comply with the Applicable WPS.

Bay#2- Segment 1AAW

SMAW welding of weld joint base metal repair of weld location Seg1F-045, 003, 046, 004 located on A-00 on Segment 1AAW. Welder is identified as 201583 (3G). ZPMC QC-CWI is identified as Li Zhi Jiang . The welding variables recorded by QC appeared to comply with the Applicable WPS.

Unless otherwise noted, all observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By: Patel,Hiranch

Quality Assurance Inspector

Reviewed By: Prue,Erik

QA Reviewer