

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-007748**Date Inspected:** 30-Jun-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 1845**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 645**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Ming**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG and Tower**Summary of Items Observed:**

Summary of Items Observed: On this date Caltrans OSM Quality Assurance (QA) Inspector, Larry Viars was present during the times noted above for observations relative to the work being performed.

Bay 2:

This Caltrans QA inspector performed Magnetic Particle Testing verification of base metal repair areas tested and accepted by ZPMC Quality Control (QC) of base metal repair areas on OBG Segment 1AAW. The following welds at location A00 were tested:

SEG1E- 124, 045, 046, 334, 416

SEG1F- 002, 003, 004, 005, 006

SEG1D- 004, 086, 088

Bay 10:

This QA Inspector observed the following work in progress: FCAW welding of weld joint SSSL3-1 I/K located on the South Tower Lift 3. ZPMC welder was identified as 201825. ZPMC QC is identified as Li Ming. The welding appeared to be in conformance with welding procedure specification, WPS-B-T-4333-TC-P4-F.

FCAW welding of weld joint SSSL3-1 G/K located on the South Tower Lift 3. ZPMC welder was identified as 057244. ZPMC QC is identified as Li Ming. The welding appeared to be in conformance with welding procedure

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

specification, WPS-B-T-4333-TC-P5-F.

Bay 11:

This QA Inspector observed the following work in progress: FCAW welding of weld joint SSSL3-1 K/K located on the West Tower Lift 3. ZPMC welder was identified as 067184. ZPMC QC is identified as Liu Xiao Zhong. The welding appeared to be in conformance with welding procedure specification, WPS-B-T-2333-TC-P4-F.

OBG Trial Assembly Area:

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The members are identified as OBG Segment 2AE Floor beams. The weld identification numbers are as follows:

FB056-001-007, 009
FB053-003- 017, 018
FB054-002-002, 005
FB048-001-008, 010

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

As identified within the contents of this report.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150 0042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Viars,Larry	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
