

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-010282**Date Inspected:** 29-Oct-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Lin.**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Amit K. Juvekar, was present during the times noted above for observations relative to the work being performed.

This QA Inspector observed the following work in progress:

Bay 11, East Tower, Lift 4, A/B & A/E Corner Seam.

SMAW welding of weld joint ESTL4-2L/L-4B, 5B; located on Bay 11, East Tower, Lift 4. Welders are identified as 058009, 091271, 046704, 040656; ZPMC Quality Control Inspector (QC) is identified as Li Lin. The welding variables recorded by Quality Control Inspector (QC) appeared to comply with the Applicable WPS: WPS-B-T-3211-TC-U4B-1.

Bay 10, East Tower, Lift 1.

1) Installing of Interior Splice Plate on Skin Plates A & B.

Bay 10, East Tower, Lift 1.

1) Installing of Interior Splice Plate on Skin Plates D & E.

This QA Inspector carried out NDE on following

Bay 11, Tower Strut Plates.

This QA inspector performs Random Ultrasonic Testing (UT) of approximately 10% area previously tested and accepted by ZPMC Quality Control personnel, FOR GREEN TAG. This QA Inspector generated an UT

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

report(TL-6027) for this date. The members are identified as

- 1) WD1-STSA3-2-99M-1-4A, 6B, 1A, 2B.
- 2) WD1-STSA3-2-99M-2-4A, 6B, 1A, 2B.
- 3) SD1-STSA3-1-89M-1-4A, 6B, 1A, 3B, 2B, 51B.
- 4) SD1-STSA3-1-99M-1-4A, 6B, 1A, 3B, 2B, 51B.
- 5) SD1-STSA3-1-109M-1-4A, 6B, 1A, 3B, 2B, 51B.

Milling Yard, East Tower, Lift 3, Padeyes.

This QA inspector performs Random Visual Testing (VT), Magnetic Particle Testing (MT) of approximately 15% area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report(TL-6028) for this date. The members are identified as Padeyes of Skin A/B/C/E.

This QA did not Inspected Padeyes on skin D due to lack of access at the Inspection area.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod, 13482570045, who represents the Office of Structural Materials for your project.

Inspected By:	Juvekar,Amit	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
