

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-011573**Date Inspected:** 18-Jan-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Mr. Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Orthotropic Box Girder (OBG)**Summary of Items Observed:**

This CALTRANS OSM Quality Assurance Inspector (QA) Surendra Prabhu was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

OBG TRIAL ASSEMBLY

This QA Inspector observed the following work in progress:

SEGMENT-6CE

Flux Cored Arc Welding (FCAW) welding of weld joint SEG032D-013. Welder is identified as 067103. ZPMC Quality Control (QC) is identified as Mr. Wang Li Yang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-T-2233-TC-U4b-F.

SEGMENT -7AE-7BE

Flux Cored Arc Welding (FCAW) welding of weld joint SP311-001-001. Welder is identified as 067665. ZPMC Quality Control (QC) is identified as Mr. Wang Li Yang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-P-2112-FCM-1.

SEGMENT -7BE

Flux Cored Arc Welding (FCAW) welding of weld joint SP365-001-001. Welder is identified as 066478. ZPMC Quality Control (QC) is identified as Mr. Wang Li Yang. The welding variables recorded by QC appeared to

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

comply with the Applicable WPS: WPS-B-P-2112-FCM-1.

SEGMENT -7AE-7BE.

Flux Cored Arc Welding (FCAW) welding of weld joint OBE7-003. Welder is identified as 220066. ZPMC Quality Control (QC) is identified as Mr. Wang Zhu. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-T-223(2)1T-2.

SEGMENT-6BE-6CE

Shielded Metal Arc Welding (SMAW) repair welding of weld joint OBE6A-003. Welder is identified as 048659. ZPMC Quality Control (QC) is identified as Mr. Wang Li Yang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-345-SMAW-4G (4F)-FCM-Repair-1 and Welding Repair Report (WRR) No: B-WR9901.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and Quality Control (QC) concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Prabhu,Surendra	Quality Assurance Inspector
Reviewed By:	Miller,Mark	QA Reviewer
