

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-012202**Date Inspected:** 08-Jan-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

<b>CWI Name:</b>	NA	<b>CWI Present:</b>	Yes	No
<b>Inspected CWI report:</b>	Yes No N/A	<b>Rod Oven in Use:</b>	Yes No N/A	
<b>Electrode to specification:</b>	Yes No N/A	<b>Weld Procedures Followed:</b>	Yes No N/A	
<b>Qualified Welders:</b>	Yes No N/A	<b>Verified Joint Fit-up:</b>	Yes No N/A	
<b>Approved Drawings:</b>	Yes No N/A	<b>Approved WPS:</b>	Yes No N/A	
		<b>Delayed / Cancelled:</b>	Yes No N/A	
<b>Bridge No:</b>	34-0006	<b>Component:</b>	OBG	

**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector Larry Viars was present during the times noted above for observations relative to the work being performed.

North of Blast Bay 1-

This QA Inspector performed Magnetic Particle Testing (MT) verification of welds previously tested and accepted by ZPMC for OBG Segment 5AW to 5BW hold back and interior transverse splice welds. See MT report TL-6028 generated this date for additional information.

OBW5A-001~005

EP037-001-001~005

EP037-001-005~008

BP029-001-043, 044, 053 and 054

BP083-001-043, 044, 053 and 054

BP030-001-041, 042, 51 and 052

BP084-001-031, 032, 041 and 042

SP145-001-050, 051, 060 and 061

SP146-001-041, 042, 051 and 052

SP118-001-050, 051, 060 and 061

SP119-001-031, 032, 041 and 042

SP91-001- 058, 059, 070 and 071

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

SP92-001-036,037, 048 and 049

Caltrans QA visually rejected SP146-001-041 hold back weld for overlap. ZPMC QC stated they would repair the overlap area and perform MT of this area.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

**Summary of Conversations:**

Only general conversation occurred between QA and QC this date.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150 0042 2372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Viars,Larry	Quality Assurance Inspector
<b>Reviewed By:</b>	McClendon,Timothy	QA Reviewer

---