

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-012686**Date Inspected:** 15-Mar-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

TRIAL ASSEMBLY YARD

MAGNETIC PARTICLE INSPECTION

OBG SEGMENT 6 WEST

This Q.A Inspector performed Magnetic particle Inspection of approximately 15% of the area previously tested and accepted by ZPMC Quality control personnel. This QA Inspector generated a (M.T) report for this date. The members are identified as the OBG segment 6AW Designation are as follows.

SP085-002-022~031; OBW6F-009; OBW6D-020, 021, 028, 029.

OBG SEGMENT 6 EAST

This Q.A Inspector performed Magnetic particle Inspection of approximately 15% of the area previously tested and accepted by ZPMC Quality control personnel. This QA Inspector generated a (M.T) report for this date. The members are identified as the OBG segment 6AW Designation are as follows.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

OBE6D-043, 049

This QA Inspector randomly observed the following work in progress.

OBG SEGMENT 7AW-7BW

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 045196 performing Shielded Metal Arc Welding process for weld SEG035A-005 located on PCMK weld between side panel and bottom panel (cross beam side). ZPMC QC Mr. Zhong Yang Gang monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-345-SMAW-4G (4F)-FCM-Repair-1. Weld repair report identified as B-WR10620.

OBG SEGMENT 7CE

This Quality Assurance (QA) Inspector observed ZPMC personnel performing carbon air arc gouging on the weld between edge panel and deck panel (bike path side).

OBG SEGMENT 6AE

This Quality Assurance (QA) Inspector observed ZPMC personnel performing sand blasting in OBG segment 6AE at FL -003 locations near the PP38, 39, 40.

OBG SEGMENT 7AE

This Quality Assurance (QA) Inspector observed ABF QA Inspector performing ultrasonic inspection for the weld between side panel and bottom panel (bike path side) in OBG segment 7AE near the PP48.

Unless otherwise noted, all work observed on this dated appeared to generally comply with applicable contract documents.



Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

for your project.

Inspected By: Utekar,Shrikant

Quality Assurance Inspector

Reviewed By: Dawson,Paul

QA Reviewer