

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-013665**Date Inspected:** 02-May-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** An Qing Xiang, Tu Jun**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

Bay 10, Lift 4 skin E Facade

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA inspector generated UT report for this date. The members are identified as Tower Components. The weld designations reviewed are as follows.

SD1-SFSA4-3A/B-19

SD1-SFSA4-1A/B-1

SD1-SFSA4-30A/B-11

SD1-SFSA4-2A/B-12

This Quality Assurance (QA) Inspector observed the following work in progress:

BAY11

TOWER GRILLAGE PLATE

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SMAW welding of weld joint 35A located on ESD1-TL5-2B/F.

Welder is identified as 040619. ZPMC CWI is identified as Mr. An Qing Xiang.

The welding variables recorded by QC appeared to comply with WPS-B-T-3213-B-U3b.

SMAW welding of weld joint 35B located on ESD1-TL5-2B/F.

Welder is identified as 040690. ZPMC CWI is identified as Mr. An Qing Xiang.

The welding variables recorded by QC appeared to comply with WPS-B-T-3213-B-U3b.

LIFT 4 STRUT PLATE

SMAW welding of weld joint 10B located on ED1-STSA4-6-131M-1.

Welders are identified as 044541 & 044551. ZPMC QC is identified as Mr. Xu Jin Long.

The welding variables recorded by QC appeared to comply with WPS-B-T-2212-Tc-U5b.

SMAW welding of weld joint 5B located on ND1-STSA4-6-127M-2.

Welder is identified as 041271. ZPMC QC is identified as Mr. Xu Jin Long.

The welding variables recorded by QC appeared to comply with WPS-B-T-3212-Tc-U5b-1.

SMAW welding of weld joint 7B located on SD1-STSA4-5-127M-1.

Welders are identified as 040667 & 040614. ZPMC QC is identified as Mr. Liu Dao Feng.

The welding variables recorded by QC appeared to comply with WPS-B-T-2212-Tc-U5b.

SMAW welding of weld joint 6B located on WD1-STSA4-5-123M-1.

Welder is identified as 046704. ZPMC QC is identified as Mr. Liu Dao Feng.

The welding variables recorded by QC appeared to comply with WPS-B-T-3212-Tc-U5b-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Skyler Guest : 15000422360, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Umesh	Quality Assurance Inspector
----------------------	---------------	-----------------------------

Reviewed By:	Clifford,William	QA Reviewer
---------------------	------------------	-------------