

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014883**Date Inspected:** 04-May-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Geng Wei, Zhu Zhong Hai.**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Orthotropic Box Girder (OBG)**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Amit K. Juvekar, was present during the times noted above for observations relative to the work being performed.

This QA Inspector observed the following work in progress:

Assembly, Bay 14, 12CW, Longitudinal Diaphragm to Bottom Plate.

FCAW Repair welding of weld joint SEG3006S-056(WRR # B-WR12506); located on assembly, Bay 14, 12CW. Welder is identified as 047866; ZPMC Quality Control Inspector (QC) is identified as Zhu Zhong Hai. The welding variables recorded by Quality Control Inspector (QC) appeared to comply with the Applicable WPS: WPS-345-FCAW-2G(2F)-REPAIR-1.

Assembly, Bay 14, 12BE, Longitudinal Diaphragm to Deck Plate.

FCAW welding of weld joint SEG3002F-001; located on assembly, Bay 14, 12BE. Welder is identified as 214945; ZPMC Quality Control Inspector (QC) is identified as Lu Li Qing. The welding variables recorded by Quality Control Inspector (QC) appeared to comply with the Applicable WPS: WPS-B-P-2233-B-U2-F.

Assembly, Bay 14, 12BE, Deck Panel to Longitudinal Diaphragm.

FCAW welding of weld joint DP3016-001-016, 017; located on assembly, Bay 14, 12BE. Welder is identified as 066179; ZPMC Quality Control Inspector (QC) is identified as Lu Li Qing. The welding variables recorded by Quality Control Inspector (QC) appeared to comply with the Applicable WPS: WPS-B-P-2213-TC-U4B-FCM-1.

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

Assembly, Bay 14, 12CE, Longitudinal Diaphragm Stiffener.

SMAW welding of weld joint SEG3003T-062, 058; located on assembly, Bay 14, 12CE. Welder is identified as 200113; ZPMC Quality Control Inspector (QC) is identified as Lu Li Qing. The welding variables recorded by Quality Control Inspector (QC) appeared to comply with the Applicable WPS: WPS-B-P-2114-FCM-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

**Summary of Conversations:**

No relevant conversations.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 1500.042.2372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Juvekar,Amit	Quality Assurance Inspector
<b>Reviewed By:</b>	Hall,Steven	QA Reviewer

---