

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-015294**Date Inspected:** 25-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Joe Alaniz was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

OBG Assembly Yard

9BE+9CE

Shield Metal Arc Welding (SMAW) welding was performed on weld joint 006 located at OBE9B cross beam of segment. Welder is identified as Mr. Zhang Feng (049769). ZPMC QC is identified as Wu Zhi Cheng. The welding variables monitored and recorded by the QC appeared to comply with WPS-B-P-2214-B-U2-FCM-1.

Shield Metal Arc Welding (SMAW) welding was performed on weld joint 007 located at OBE9B cross beam of segment. Welder is identified as Mr. Han Zhao Feng (054467). ZPMC QC is identified as Wu Zhi Cheng. The welding variables monitored and recorded by the QC appeared to comply with WPS-B-P-2214-B-U2-FCM-1.

9AW

Shield Metal Arc Welding (SMAW) VT repair welding was performed various locations on the FL3 horizontal and bottom plate stiffeners cross beam side of segment. Welder is identified as Mr. Ni Leijiang (037723). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

WPS-345-SMAW-2G (2F)-Repair-1 and CWR1414 procedure.

Shield Metal Arc Welding (SMAW) VT repair welding was performed various locations on the bottom plate stiffeners cross beam side of segment. Welder is identified as Mr. Zhang Quanfa (066326). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with WPS-345-SMAW-2G (2F)-Repair-1 and CWR1414 procedure.

## Miscellaneous Work In Progress

QA Inspector observed ZPMC's personnel performing various job functions at Tail Assembly Yard. Locations and description of work are as followed:

8 East and 8 West

1. Sea fasteners and cable trays are being installed at various locations inside segment.

9BE+9CE

1. Back gouging being performed on the side plate splice located at cross beam side of segment.

NOTE: Due to inclement weather work was limited in the Trail Assembly Yard.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

### Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (150-0042-2372), who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Alaniz,Joe	Quality Assurance Inspector
<b>Reviewed By:</b>	Carreon,Albert	QA Reviewer

---