

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1x.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-015372**Date Inspected:** 27-Apr-2010**Project Name:** SAS Superstructure**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Arrival Time:** 630**OSM Departure Time:** 1600**Location:** Jobsite Pier 7**CWI Name:****CWI Present:**

Yes No

Inspected CWI report: Yes No N/A**Rod Oven in Use:**

Yes No N/A

Electrode to specification: Yes No N/A**Weld Procedures Followed:**

Yes No N/A

Qualified Welders: Yes No N/A**Verified Joint Fit-up:**

Yes No N/A

Approved Drawings: Yes No N/A**Approved WPS:**

Yes No N/A

Delayed / Cancelled:

Yes No N/A

Bridge No: 34-0006**Component:** OBG Lift 5E**Summary of Items Observed:**

Post arrival inspection of OBG Lift 5E.

By 0730 hours I met with Structures Construction and our METS counterparts to inspect OBG Lift 5E Panel Points 33 to 35. I inspected these locations with Matt Bruce of Caltrans Structures Construction. There did not appear to be any damage due to transporting this OBG segment from China.

Summary of Conversations:**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mohammad Fatemi (916) 813-3677, who represents the Office of Structural Materials for your project.

Inspected By: Gramlick, Jason

Quality Assurance Inspector

Reviewed By: Fatemi, Mohammad

QA Reviewer