

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-016917**Date Inspected:** 24-Sep-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Liu Hua Jie.**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG components.**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Mr. Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

OBG Trial Assembly Yard:

This QA Inspector observed the following work in progress:

OBG Seg 11AW:

The Shielded Metal Arc Welding (SMAW) process on weld joint no: CA080-006. The welder is identified as 044551 and was observed welding in the 4G position. ZPMC Quality Control (QC) was identified as Zhu Zhong Hai. The welding variables recorded by QC appeared to comply with WPS: B-P-2214-TC-U4b-FCM-1.

OBG Seg 10CW:

The SMAW process on weld joint no: SEG063*-036. The welder is identified as 044551 and was observed welding in the 4G position. ZPMC QC was identified as Zhu Zhong Hai. The welding variables recorded by QC appeared to comply with WPS: B-P-2214-TC-U4b-FCM-1.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

OBG Seg 10BW:

Repair welding of weld joint no: OBW10L-005. Welding process was identified as SMAW. The welder was identified as 046709 and was observed welding in the 1G position. ZPMC QC was identified as Zhu Zhong Hai. The welding variables recorded by QC appeared to comply with WPS: 345-SMAW-1G(1F)-Repair. Repair welding was done as per Welding Repair Report WRR: B-WR-15233 Rev-0.

Repair welding of weld joint no: OBW10L-006. Welding process was identified as SMAW. The welder was identified as 046709 and was observed welding in the 4G position. ZPMC QC was identified as Zhu Zhong Hai. The welding variables recorded by QC appeared to comply with WPS: 345-SMAW-4G(4F)-Repair. Repair welding was done as per Welding Repair Report WRR: B-WR-15234 Rev-0.

OBG Seg 10BE and Seg 10CE:

The SMAW process on weld joint no: DP702-001-039. The welder is identified as 044515 and was observed welding in the 3G position. ZPMC QC was identified as Wang Liang. The welding variables recorded by QC appeared to comply with WPS: B-T-3213-B-U3b.

The SMAW process on weld joint nos: DP715-001-019, 020 and 021. The welder is identified as 057266 and was observed welding in the 3G position. ZPMC QC was identified as Wang Liang. The welding variables recorded by QC appeared to comply with WPS: B-T-3213-B-U3b.

OBG Seg 10CE:

The Flux Cored Arc Welding (FCAW) process on weld joint no: SEG064B-031. The welder is identified as 047353 and was observed welding in the 1G position. ZPMC QC was identified as Zhang Xian Ming. The welding variables recorded by QC appeared to comply with WPS: B-T-2231-TC-U4b-F.

The SMAW process on weld joint no: SEG064B-011. The welder is identified as 044504 and was observed welding in the 3G position. ZPMC QC was identified as Wang Liang. The welding variables recorded by QC appeared to comply with WPS: B-P-2213-TC-U4b-FCM-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372., who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By:	Wadkar,Sailesh	Quality Assurance Inspector
----------------------	----------------	-----------------------------

Reviewed By:	Peterson,Art	QA Reviewer
---------------------	--------------	-------------
