

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-016922**Date Inspected:** 26-Sep-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Lv Li Qing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance(QA) Inspector Mr. Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. The QA Inspector observed and/or found the following:

This QA Inspector randomly observed the following work in progress.

BAY # 14

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 070478 performing the Flux Cored Arc Welding process on weld 037 located at PCMK VP3007-001. ZPMC QC Mr. Lv Li Qing was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2232-Tc-u4b-f.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 067520 performing the Flux Cored Arc Welding process on weld 012 located at PCMK VP3007-001. ZPMC QC Mr. Lv Li Qing was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2232-Tc-u4b-f.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 044824 performing the Flux Cored Arc Welding process on weld 017 located at PCMK VP3005-001. ZPMC QC Mr. Lv Li Qing was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2232-Tc-u4b-f.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066763 performing the Flux Cored Arc

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Welding process on weld 007 located at PCMK VP3016-001. ZPMC QC Mr. Lv Li Qing was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2232-Tc-u4b-f.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 045196 performing the Shielded Metal Arc Welding process on weld 002 located at PCMK SEG3013AC-002. ZPMC QC Mr. Xia Chun Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-345-SMAW- 1G (1F)-Fcm-Repair. Weld repair report identified as B-WR15256.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 202122 performing the Flux Cored Arc Welding process on weld 003 located at PCMK SEG3015. ZPMC QC Mr. Xia Chun Hui was monitoring this welding operation. The welding variables recorded by QC appeared to comply with WPS-B-T-2231-B-u2-f.

This QA Inspector observed ZPMC personnel performing Magnetic Particle inspection on bottom plate temporary attachment removed areas of OBG segment 13AW.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By: Utekar,Shrikant

Quality Assurance Inspector

Reviewed By: Peterson,Art

QA Reviewer