

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-018557**Date Inspected:** 06-Dec-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Xu Xian Ping
Inspected CWI report: Yes No N/A
Electrode to specification: Yes No N/A
Qualified Welders: Yes No N/A
Approved Drawings: Yes No N/A

CWI Present: Yes No
Rod Oven in Use: Yes No N/A
Weld Procedures Followed: Yes No N/A
Verified Joint Fit-up: Yes No N/A
Approved WPS: Yes No N/A
Delayed / Cancelled: Yes No N/A

Bridge No: 34-0006**Component:** Orthotropic Box Girder (OBG)**Summary of Items Observed:**

On this date Caltrans Office of Structural Material (OSM) Quality Assurance (QA) Inspector, D.Sukanthan was present during the time noted above for observations relative to the work being performed.

This QA Inspector randomly observed the following work in progress:

OBG # CROSSBEAM CB15

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG # CROSSBEAM CB16

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG # CROSSBEAM CB17

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG # CROSSBEAM CB18

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG # CROSSBEAM CB19

This QA observed ZPMC qualified welding personnel identified as 215083 perform Shielded Metal Arc Welding (SMAW) Process on weld joint CB3003J-001-017,018. ZPMC Quality Control Personnel (QC) identified as Mr. Xu hai yang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2113-FCM.

This QA observed ZPMC qualified welding personnel identified as 057795 perform Shielded Metal Arc Welding (SMAW) Process on weld joint FB3246-002-037. ZPMC Quality Control Personnel (QC) identified as Mr. Xu hai yang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2212-B-U2-FCM.

This QA observed ZPMC qualified welding personnel identified as 054467 perform Shielded Metal Arc Welding (SMAW) Process on weld joint DP3180-2-001-018. ZPMC Quality Control Personnel (QC) identified as Mr. Xu hai yang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2213-TC-U4b.

This QA observed ZPMC qualified welding personnel identified as 049769 perform Shielded Metal Arc Welding (SMAW) Process on weld joint DP3178-1-001-010. ZPMC Quality Control Personnel (QC) identified as Mr. Xu hai yang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2213-TC-U4b.

OBG # SEGMENT 12CW

This QA Inspector performed a preliminary random visual inspection on OBG Segment 12CW at panel point 115 to panel point 117, after the grit blast of the internal components of the Bottom panel and Side Panel of this segment. Areas of visual weld defects that will require welding were taped and will be repaired after the coating is applied. ZPMC QC personnel are aware of these areas and were present during the inspection.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

As mention above

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-00422372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By:	Sukanthan,Dhanasingh	Quality Assurance Inspector
----------------------	----------------------	-----------------------------

Reviewed By:	Hall,Steven	QA Reviewer
---------------------	-------------	-------------