

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-018672**Date Inspected:** 03-Dec-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2400**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** ShangHai, China**CWI Name:** Tian Lei**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

Summary of Items Observed: On this date Caltrans OSM Quality Assurance(QA) Inspector, DJ Shin was present during the times noted above for observations relative to the work being performed.

Bay 2

This QA Inspector observed the following work in progress for Bay 2.

ZPMC was using the Shield Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Tian Lei.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specifications (WPS). Listed below are the locations that were identified by this QA inspector.

Components: Grillage Assembly

PCMK: SA7512-001-031

Welder: 067942

Report: B-CWR 2352

WPS-345-SMAW-3G (3F)-Repair

PCMK: SA7512-001-032

Welder: 066674

Report: B-CWR 2353

WPS-345-SMAW-3G (3F)-Repair

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

PCMK: SA7512-001-060

Welder: 066673

Report: B-CWR 2308

WPS-345-SMAW-3G (3F)-Repair

This QA Inspector observed the following work in progress for Bay 2.

ZPMC was using the Flux Core Arc Welding (FCAW) process.

ZPMC QC is identified as Tian Lei.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specifications (WPS). Listed below are the locations that were identified by this QA inspector.

Components: Floor Beam

PCMK: FB3343-001-337

Welder: 066239

Report: B-CWR 2352

WPS-B-T-2232-ESAB

This QA inspector performed Ultrasonic Testing (UT) of approximately 10 % of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member(s) is/are identified as follows; FB3343-001, on Item number 1 of NWIT tracker document # 07611,

Bay 8

This QA inspector performed Ultrasonic Testing (UT) of approximately 10 % of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member(s) is/are identified as follows; BK004A, on Item number 2, 3, 4, 5 of NWIT tracker document # 07606,

Bay 14

This QA inspector performed Magnetic Particle Testing (MT) and Visual Inspection (VT) of approximately 100 % of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member(s) is/are identified as follows; FB3286-001, on item number 1 of NWIT tracker document # 07606,

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By:	Shin,DJ	Quality Assurance Inspector
----------------------	---------	-----------------------------

Reviewed By:	Carreon,Albert	QA Reviewer
---------------------	----------------	-------------