

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-020262**Date Inspected:** 10-Oct-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Yu Dong Ping, Qiu Wen**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG/TOWER**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

BAY 11, OBG BIKE PATH (NWIT # 06907)

This QA inspector performed random Visual Testing (VT) of the area previously tested and accepted by ZPMC Quality Control personnel. The members are identified as OBG Components. The weld designations reviewed are as follows.

BK004A3-017-065, 067~71, 100~105

BK004A4-017-080, 082, 083, 085~087, 100~105

BAY 12, OBG (NWIT # 06909, GREEN TAG NO. 15055)

This QA inspector performed Ultrasonic Testing (UT) of approximately more than 10% lot testing of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT reports for this date. The members are identified as OBG Components. The weld designations reviewed are as follows.

SA3084A-033-001, 002

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SA3051A-030-001, 002

This Quality Assurance (QA) Inspector observed the following work in progress:

BAY 10, OBG BIKE PATH

FCAW welding of weld joints 033 located on BK004A8-025.

Welder is identified as 053869. ZPMC QC is identified as Mr. Yu Zhi Lai.

The welding variables recorded by QC appeared to comply with WPS-B-T-2133.

FCAW welding of weld joints 031 located on BK004A6-025.

Welder is identified as 052075. ZPMC QC is identified as Mr. Yu Zhi Lai.

The welding variables recorded by QC appeared to comply with WPS-B-T-2133.

SMAW welding of weld joints 008 located on BK004A1-025.

Welders are identified as 052930, 056364 & 052493. ZPMC QC is identified as Mr. Yu Zhi Lai.

The welding variables recorded by QC appeared to comply with WPS-B-T-2133.

BAY 11, OBG BIKE PATH

FCAW welding of weld joint 027 located on BK004A6-021.

Welder is identified as 042218. ZPMC QC is identified as Mr. Zhao Mao Mao.

The welding variables recorded by QC appeared to comply with WPS-B-T-2133.

SMAW welding of weld joints 009 located on BK004A6-021.

Welder is identified as 054460. ZPMC QC is identified as Mr. Wang Cheng Xin.

The welding variables recorded by QC appeared to comply with WPS-B-P-2114.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang : 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Umesh	Quality Assurance Inspector
----------------------	---------------	-----------------------------

Reviewed By:	Carreon,Albert	QA Reviewer
---------------------	----------------	-------------